

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Date Received:
01/27/2011

Document Number:
1771177

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 16660 Contact Name: LINDSEY MELOTT
 Name of Operator: CHESAPEAKE OPERATING INC Phone: (405) 935-8323
 Address: P O BOX 18496 Fax: (405) 849-8323
 City: OKLAHOMA CITY State: OK Zip: 73154-04 Email: LINDSEY.MELOTT@CHK.COM

For "Intent" 24 hour notice required, COGCC contact: Name: LONGWORTH, MIKE Tel: (970) 812-7644
 Email: _____

API Number 05-103-09879-00
 Well Name: S WRD FEDERAL Well Number: 1-27
 Location: QtrQtr: NENW Section: 27 Township: 2N Range: 97W Meridian: 6
 County: RIO BLANCO Federal, Indian or State Lease Number: 38292
 Field Name: WHITE RIVER Field Number: 92800

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.118077 Longitude: -108.265289
 GPS Data:
 Data of Measurement: 09/24/2010 PDOP Reading: 2.3 GPS Instrument Operator's Name: Roth
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Top of Casing Cement: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Code	Perf. Top	Perf. Bottom	Date	Method of Isolation	Plug Depth
WASATCH	WSTC	891	1343	10/20/2009	CEMENT	0

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	8+3/4	7	20	319	165	319	0	VISU
1ST	6+1/4	4+1/2	10.5	1,432	165	1,432	0	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 1050 with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 80 sks cmt from 1050 ft. to 235 ft. in Plug Type: CASING Plug Tagged:
Set 20 sks cmt from 235 ft. to 0 ft. in Plug Type: CASING Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
Set _____ sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: 10/20/2009
*Wireline Contractor: _____ *Cementing Contractor: Western Wellsite Services
Type of Cement and Additives Used: 15.8#, Class "G", Neat
Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: LINDSEY MELOTT
Title: SR REG COMP SPEC Date: 1/26/2011 Email: LINDSEY.MELOTT@CHK.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KOEHLER, BOB Date: 3/2/2011

CONDITIONS OF APPROVAL, IF ANY:

Attachment Check List

Att Doc Num	Name
1771177	FORM 6 SUBSEQUENT SUBMITTED
2110822	OTHER
2110824	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Data Entry	WASATCH 1116'-1343', BRIDGE PLUG 1050', 12/6/1997 WASATCH 891'-924', CEMENT WELLBORE, 1050'-0', 10/20/09	2/25/2011 2:13:40 PM

Total: 1 comment(s)