

Jolley KP 541-28

KP 541-28, KP 441-28, KP 511-27, KP 521-27, KP 411-27, KP 421-27, KP 311-27,
 KP 321-27, KP 21-27, KP 11-27, KP 341-28, KP 41-28, KP 544-21, KP 444-21,
 KP 344-21, KP 44-21, KP 543-21, KP 443-21, KP 343-21, KP 43-21



PHOTO: VIEW FROM PAD CENTER

CAMERA ANGLE: NORTH



PHOTO: VIEW FROM PAD CENTER

CAMERA ANGLE: SOUTH



PHOTO DATE: 2/23/11
 TAKEN BY: JK
 DRAWN BY: WKK
 SHEET: 1 of 3
 PROJECT: Williams

LOCATION PHOTOS Prepared for:
Williams Williams Production, RMT
 NE1/4 NW1/4, SECTION 28
 T. 6 S., R. 91 W. of the 6th. P.M.
 GARFIELD COUNTY, COLORADO

Jolley KP 541-28

KP 541-28, KP 441-28, KP 511-27, KP 521-27, KP 411-27, KP 421-27, KP 311-27,
KP 321-27, KP 21-27, KP 11-27, KP 341-28, KP 41-28, KP 544-21, KP 444-21,
KP 344-21, KP 44-21, KP 543-21, KP 443-21, KP 343-21, KP 43-21



PHOTO: VIEW FROM ACCESS ROAD

CAMERA ANGLE: EAST



PHOTO: VIEW FROM PAD CENTER

CAMERA ANGLE: WEST

LOCATION PHOTOS Prepared for:



Williams Production, RMT

NE1/4 NW1/4, SECTION 28
T. 6 S., R. 91 W. of the 6th. P.M.
GARFIELD COUNTY, COLORADO

2011 Book Cliffs Survey Services, Inc.
PO Box 1000
P.O. Box 1000
P.O. Box 1000



BOOKCLIFFS
Survey Services, Inc.

PHOTO DATE: 2/24/11
TAKEN BY: JK
DRAWN BY: WKK
SHEET: 2 of 3
PROJECT: Williams

Jolley KP 541-28

KP 541-28, KP 441-28, KP 511-27, KP 521-27, KP 411-27, KP 421-27, KP 311-27,
KP 321-27, KP 21-27, KP 11-27, KP 341-28, KP 41-28, KP 544-21, KP 444-21,
KP 344-21, KP 44-21, KP 543-21, KP 443-21, KP 343-21, KP 43-21



PHOTO: VIEW OF OVERALL DRILL PAD

CAMERA ANGLE: NORTHWEST



PHOTO: VIEW OF PROPOSED ACCESS ROAD

CAMERA ANGLE: NORTH

LOCATION PHOTOS Prepared for:



Williams Production, RMT

NE1/4 NW1/4, SECTION 28

T. 6 S., R. 91 W. of the 6th. P.M.

GARFIELD COUNTY, COLORADO

Bookcliff Survey Services, Inc.
PO Box 1000
P.O. Box 1000
P.O. Box 1000



BOOKCLIFF
Survey Services, Inc.

PHOTO DATE: 2/24/11
TAKEN BY: JK
DRAWN BY: WKK
SHEET: 3 of 3
PROJECT: Williams