



Geologist Information

General: Existing location, 3 new wells (4 existing)
 Ownership: Bosely Surface/ Fee minerals
 SUA Status: Needs amending
 Spacing Units: 2 spacing units – NE/4 and E/2SE/4 section 27
 Adjacent Owners: Powers, Tipping, Specialty Rest.

Plan of Development

Access: Use existing access
 Drilling: Efficiency rig
 Cuttings: In trench on location
 SIMOPS: No
 Completion: Frac on pad or from frac pad on Sales property
 Flowback: on pad
 Prod Equip: Production equipment to be set on northern end of pad.
 Pipeline: No new lines needed.



- Legend**
- Existing Road
 - Pipeline (Valley)
 - - - - Proposed Production Equipment Area
 - Existing Production Equipment
 - - - - Proposed Daylight Line
 - Proposed Pad or Pit
 - x-x-x-x Existing Fence
 - Williams Surface

Williams Production RMT
 SG 43-27 Plan of Development
 T7S R96W, Section 27

July 22, 2010

