

HRM RESOURCES LLC
555 17th Street, Suite #950
Denver CO 80202
(o) 303-893-6621 (f) 303-893-6892

03/21/11

Colorado Oil and Gas Conservation Commission
Attn: David Neslin, Director
1120 Lincoln Street, Suite 801
Denver, CO 80203

RE: Rule 318.A Exception Location Request

Boulter #0-2-27 Well: 1418' FNL, 1465' FWL

Boulter #2-2-27 Well: 1418' FNL, 1490' FWL

SENE Sec. 27-T5N-R65W, Weld County, Colorado

Dear Mr. Neslin,

HRM Resources, LLC respectfully requests that the Director grant an exception to Rule 603.a(2) for the above wells. These wells are spotted as above, on a single site and in accordance with the wishes of the surface owner, in order to maximize future land use possibilities and minimize surface disturbance. Per COGCC Rule 603.a(2), a well shall be located no less than 150' from a surface property line. As spotted, these wells are both 100' from the nearest property line. The offsetting affected surface owner, Mr. Howard Moran, has consented to these locations via the attached waiver.

Should you have any questions please contact Clayton Doke at 970-669-7411 or 720-560-2700.

Sincerely,



Clayton L. Doke for
Andy Peterson, VP Operations
HRM Resources, LLC

Cc: HRM Resources, LLC

Encl.