


<b>FORM</b> <b>6</b> Rev 12/05	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">DE</td> <td style="width: 25%;">ET</td> <td style="width: 25%;">OE</td> <td style="width: 25%;">ES</td> </tr> </table> Date Received:  05/04/2011  Document Number:  1635790	DE	ET	OE	ES
DE	ET	OE	ES				
<b>WELL ABANDONMENT REPORT</b>							
<p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.</p> <p>A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p>							
OGCC Operator Number: <u>71450</u>		Contact Name: <u>ROBERT VACLAVIK</u>					
Name of Operator: <u>PONCHO PRODUCTION CO</u>		Phone: <u>(580) 696-2883</u>					
Address: <u>HC 2 BOX 14</u>		Fax: <u>(580) 696-2883</u>					
City: <u>KEYES</u>	State: <u>OK</u>	Zip: <u>73947</u>	Email: <u>RPVAC@WILDEBLUE.NET</u>				
<b>For "Intent" 24 hour notice required, COGCC contact:</b>							
Name: <u>LEONARD, MIKE</u>		Tel: <u>(719) 647-9715</u>					
Email: <u>mike.leonard@state.co.us</u>							
API Number <u>05-009-06079-00</u>							
Well Name: <u>HAMILTON, LESTER</u>		Well Number: <u>1</u>					
Location: QtrQtr: <u>NESW</u>	Section: <u>34</u>	Township: <u>34S</u>	Range: <u>41W</u>				
Meridian: <u>6</u>		County: <u>BACA</u>					
Federal, Indian or State Lease Number: <u>8455</u>		Field Name: <u>GREENWOOD</u>					
Field Number: <u>33250</u>							
<input type="checkbox"/> Notice of Intent to Abandon <input checked="" type="checkbox"/> Subsequent Report of Abandonment							
<i>Only Complete the Following Background Information for Intent to Abandon</i>							
Latitude: <u>37.038290</u>		Longitude: <u>-102.047639</u>					
GPS Data:							
Data of Measurement: <u>04/28/2009</u>		PDOP Reading: <u>1.8</u>					
GPS Instrument Operator's Name: <u>Burt West</u>							
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production for Sub-economic <input type="checkbox"/> Mechanical Problems							
<input type="checkbox"/> Other							
Casing to be pulled: <input type="checkbox"/> Yes <input type="checkbox"/> No		Top of Casing Cement:					
Fish in Hole: <input type="checkbox"/> Yes <input type="checkbox"/> No		If yes, explain details below					
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input type="checkbox"/> No		If yes, explain details below					
Details:							
<b>Current and Previously Abandoned Zones</b>							
Formation	Perf. Top	Perf. Btm	Abandoned Date				
Method of Isolation	Plug Depth						
RED CAVE	1266	1294	04/21/2010				
CEMENT							
Total: 1 zone(s)							
<b>Casing History</b>							
Casing Type	Size of Hole	Size of Casing	Weight Per Foot				
Setting Depth	Sacks Cement	Cement Bot	Cement Top				
Status							
SURF	9	7	20				
1,259	450	1,259					

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 48 sks cmt from 1234 ft. to 996 ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set 8 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing

Plugging Date: 04/21/2010

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: TORBET, INC.

Type of Cement and Additives Used: COMMON

Flowline/Pipeline has been abandoned per Rule 1103 ☒ Yes ☐ No

\*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: ROBERT L VACLAVIK

Title: PRESIDENT

Date: 4/27/2011

Email: RPVAC@WILDBLUE.NET

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK

Date: 5/19/2011

**CONDITIONS OF APPROVAL, IF ANY:**

**IMPORTANT: SOME DATA FIELDS HAVE BEEN MODIFIED.**

### **Attachment Check List**

Att Doc Num	Name
1635790	FORM 6 SUBSEQUENT SUBMITTED
1635791	CEMENT JOB SUMMARY
1635792	WELLBORE DIAGRAM

Total Attach: 3 Files

### **General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>

Total: 0 comment(s)