

<b>FORM</b> <b>6</b> Rev 12/05	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
			Date Received:  06/02/2011  Document Number:  1635203

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.  
 A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>3085</u>	Contact Name: <u>BILL SCRIBNER</u>
Name of Operator: <u>ANDRIKOPOULOS RESOURCES* A G</u>	Phone: <u>(370) 634-4441</u>
Address: <u>P O BOX 788</u>	Fax: <u>(307) 634-4445</u>
City: <u>CHEYENNE</u> State: <u>WY</u> Zip: <u>82003-07</u>	Email: <u>WRA-AGARI@BRESNAN.NET</u>
<b>For "Intent" 24 hour notice required, COGCC contact:</b>	
Name: <u>NEIDEL, KRIS</u>	Tel: <u>(970) 819-9609</u>
Email: <u>kris.neidel@state.co.us</u>	

API Number <u>05-081-06769-00</u>	Well Name: <u>ELK SPRINGS UNIT</u>	Well Number: <u>44-7</u>
Location: QtrQtr: <u>SESE</u> Section: <u>7</u> Township: <u>4N</u> Range: <u>98W</u> Meridian: <u>6</u>	County: <u>MOFFAT</u> Federal, Indian or State Lease Number: _____	
Field Name: <u>WINTER VALLEY</u>	Field Number: <u>94005</u>	

Notice of Intent to Abandon       Subsequent Report of Abandonment

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 40.326620 Longitude: -108.428480

GPS Data:  
 Date of Measurement: \_\_\_\_\_ PDOP Reading: \_\_\_\_\_ GPS Instrument Operator's Name: \_\_\_\_\_

Reason for Abandonment:    Dry       Production for Sub-economic       Mechanical Problems  
 Other \_\_\_\_\_

Casing to be pulled:    Yes       No      Top of Casing Cement: \_\_\_\_\_

Fish in Hole:    Yes       No      If yes, explain details below

Wellbore has Uncemented Casing leaks:    Yes       No      If yes, explain details below

Details: \_\_\_\_\_

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
MINTURN	9092	9266	04/15/1993	B PLUG CEMENT TOP	9040
PHOSPHORIA	7664	7730			
WEBER	7856	7864	04/15/1999	B PLUG CEMENT TOP	7800
Total: 3 zone(s)					

**IMPORTANT: SOME DATA FIELDS HAVE BEEN MODIFIED.**

### Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	17+1/4	13+3/8	54.5	300	310	300	0	VISU
1ST	12+1/4	9+5/8	36	1,002	360	1,002	0	CALC
2ND	7+7/8	5+1/2	17	9,241	1,869	9,241	3,540	CALC

### **Plugging Procedure for Intent and Subsequent Report**

CIBP #1: Depth 7615 with 2 sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:

Perforate and squeeze at 1052 ft. with 50 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at 350 ft. with 50 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged:

Set 50 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103  Yes  No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: WILLIAM R SCRIBNER

Title: VICE PRESIDENT Date: 4/15/2011 Email: WRS-AGARI@BRESNAN.NET

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRABACHER, JAY Date: 6/2/2011

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_ Expiration Date: 12/1/2011

**IMPORTANT: SOME DATA FIELDS HAVE BEEN MODIFIED.**

GPS data as per COGCC Rule 215 required with (or before) subsequent Form 6. Also added the surface perf-&-squeeze (at 350').

No GPS or well bore diagrams are provided, 5 1/2" casing not mentioned. Will send COA stating: GPS data and wellbore diagrams must be provided, casing history is to be updated. GPS can be provided on Form 6 SUBSEQUENT. (Form 6 INTENT will be ON HOLD until wellbore diagrams and casing history provided.) Well bore diagrams received. OK. dhs

**Attachment Check List**

Att Doc Num	Name
1635203	FORM 6 INTENT SUBMITTED

Total Attach: 1 Files

**General Comments**

User Group	Comment	Comment Date
Engineer	Sent request to opr to update this form. Basically, same as what D Sharp requested; but also should include surf-shoe plug and one more formation/zone. 5/27: OPR sent GPS info, but not in required format (also no PDOP, opr name, date).	5/10/2011 9:00:20 AM

Total: 1 comment(s)