



CEMENTER'S WELL SERVICE, INC.

P.O. BOX 338220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7132

OUR INVOICE

198356

AUG 18 2010

(PO # 66023)

Date 8-14-10	Well Owner SYNERGY RESOURCES	Well No. 10TD	Lease SRM+T
County WELD	State COLORADO		Field
Charge to ENSIGN US DRILLING			Charge Code
Address PO BOX 17805 (ENSIGN-33)			For Office Use Only
City, State DENVER COLORADO 80217			
Pump Truck No. 1202	Code	Bulk Truck No. 1207	Code
Type of Job		Depth 570	To
Surface 8 5/8" CSG-244		Bottom of Surface 560	To
Plug		Plug Landed @ 517	Ft. Time On 0200
Production		Pipe Landed @ 560	Ft. PLUG DOWN 0500

Reference No.	Description	Qty.	Mens.	Unit Price	Amount		
	Pump Truck Charge						
	Cement Neat ✓	400	SKS		7840 00		
	Poz. Mix						
	Calcium Chloride	3%					
	Gel % Flo-Cele 1/4 #Per Sack						
	Handling Charge						
	Handling Charge						
	Additional Cement						
8 5/8"	CENTRALIZERS	2		70 00	140 00		
"	CEMENT BASKETS	2		375 00	750 00		
"	GUIDE SHOE	1			375 00		
"	BAFFLE PLATE	1			200 00		
	BOX THROAT LOCK	1			30 00		
DISP RATE 4 BPM	SLURRY VOL 1.18	FT/SK	-WATER TEMP	70°F			
DISP RATE 5 BPM	SLURRY WT 15.2	PPG					
PLUG LAND @ 600 PSI	TOTAL SLURRY VOL 84	BBL	CEMENT				
PREFLUSH 12/20 BBL H2O	Tax Reference Code		Sub Total	9335	00		
DISPLACE W/ 32.5 BBL H2O	State CO2.9 %		Tax	270	72		
CIRCULATE 6 BBL CEMENT	Disc.		Total	9605	72		
Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1202		Pump Truck		16			
1207		Bulk Truck		16			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Joe, Josh, Kerry

Received By Jeremy Pugh
Customer or His Agent