



CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198681

(PO. # 87526)

Date 11-20-10	Well Owner SYNERGY	Well No. 24-15D	Lease RBF
County WELD	State COLORADO	Field	
Charge to ENSIGN US DRILLING	Charge Code		For Office Use Only
Address PO BOX 17805 (ENSIGN-33)			
City, State DENVER COLORADO 80217			
Pump Truck No. 1202	Code	Bulk Truck No. 1217	Code
Type of Job	Depth	Ft. 473	To
Surface 8 5/8" CSG - 24#	Bottom of Surface	Ft. 460	To
Plug	Plug Landed @ 414	Ft.	Time On 0645
Production	Pipe Landed @ 460	Ft.	Time Off Plug down 1015

Reference No.	Description	Qty.	Meas.	Unit Price	Amount		
	Pump Truck Charge						
	Cement Neat ✓ 100% EXCESS	330	SKS		6818	00	
	Poz. Mix						
	Calcium Chloride	3%					
	Gel % Flo-Cele 1/4 #Per Sack						
	Handling Charge						
	Hauling Charge						
	Additional Cement	40	SKS	14. ⁶⁰	584	00	
8 5/8"	CENTRALIZER	1			60	00	
"	CEMENT BASKET	2		300 ⁰⁰	600	00	
"	GUIDE SHOE	1			300	00	
"	BAFFLE PLATE	1			150	00	
	BOX THREADLOCK	1			30	00	
MIX RATE 4	BPM	SLURRY VOL 1.18	FT ³ /SK				
DISP. RATE 5	BPM	SLURRY WT 15.2	PPG				
PLUG LANDED @ 600 PSI	TOTAL SLURRY VOL	77.5	BBL	CEMENT			
Remarks: PREFLUSH W/ 20	BBL H ₂ O	Tax Reference Code	Sub Total		8542	00	
DISPLACE W/ 20	BBL H ₂ O	State CO 2.9 %	Tax		247	72	
CIRCULATE 5	BBL CEMENT	Disc.	Total		8789	72	
Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1202		Pump Truck		32			
1217		Bulk Truck		32			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Joe, Josh, KERRY, EVAN

Received By Ephraim Isaac
Customer or His Agent