

**From:** [Axelson, John](#)  
**To:** [Gene; gfritzier@live.com](mailto:gfritzier@live.com)  
**Cc:** [Baldwin, Debbie](#); [Lindblom, Steven](#); [Gowen, Peter](#); [Scan, OGCC](#)  
**Subject:** Gebauer #1 NOAV #200273766 Update Request  
**Date:** Monday, October 10, 2011 10:45:58 AM  
**Attachments:** [Fritzler Gebauer #1 Insp 8-18-11.pdf](#)

---

Gene,

Please provide an update regarding the corrective actions being performed at the Gebauer #1. When we met in May earlier this year a revised schedule of August 31, 2011, was established to meet the corrective actions. I stopped by the location on August 18, 2011, and it was evident that some of the site work had been performed. COGCC still requires the following information:

- Form 27 with soil sample results to verify all impacted material was removed from the pit complex;
- Form 27 needs to include soil disposal documentation for any oily waste removed from the pits;
- Form 15 to document pit upgrades to a lined facility;
- Form 2A

A copy of the most recent inspection is attached for your records.

Thank you,

John Axelson, P.G.  
Environmental Protection Specialist, Northeast Region  
Colorado Oil & Gas Conservation Commission  
Phone: 303-637-7178  
Cell: 303-877-9964  
Fax: 303-637-7179

Cc. NOAV #200273766 - Correspondence