



CEMENTER'S WELL SERVICE, INC.
P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

200190

(P.O. # 1165850)

Date 10/3/11	Well Owner Synergy	Well No. 36CD	Lease Haythorn
County Weld	State Colorado		Field
Charge to ENSIGN US Drilling			Charge Code
Address P.O. Box 17805 (ENSIGN-33)			For Office Use Only
City, State Denver, Colorado 80217			
Pump Truck No. 1208	Code	Bulk Truck No. 1214	Code
Type of Job		Depth	Ft. 535
Surface 8 5/8" CSG-24"		Bottom of Surface	Ft. 517
Plug		Plug Landed @ 475	Ft. Time On 2040
Production		Pipe Landed @ 517	Ft. Time Off Plug Down 2345

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓ 100% Excess	370	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele 1/4 #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement	600	SKS	14.85	
8 5/8"	Centralizers	3			
"	Cement Basket	1			
"	Guide Shoe	1			
"	Baffle Plate	1			
	Box thread lock	1			
	Mixing Rate - 4 BPM / Displacement Rate - 4 BPM				
	Slurry Vol - 1.18 CU FT/SK Slurry WT 15.2 PPG / Water Temp 61°F				
	Total Slurry Vol - 90.3 BBLs Cement / Landed Plug 6 300 PSI				
Remarks: Pre-Flush w/ 30 BBLs H2O	Tax Reference Code	Sub Total			
Displace w/ 30.2 BBLs H2O	State CO 2.9 %	Tax			
Circulate 3 BBLs Cement	Disc.	Total			

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1208		Pump Truck		22			
1214		Bulk Truck		22			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.