

FORM
5A

Rev
06/12

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400264170

Date Received:

03/22/2012

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 100185
2. Name of Operator: ENCANA OIL & GAS (USA) INC
3. Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-
4. Contact Name: Marina Ayala
Phone: (720) 876-5905
Fax: (720) 876-6905

5. API Number 05-045-18702-00
6. County: GARFIELD
7. Well Name: N. Parachute
Well Number: MF11A-16 H17 69
8. Location: QtrQtr: SENE Section: 17 Township: 6S Range: 96W Meridian: 6
9. Field Name: GRAND VALLEY Field Code: 31290

Completed Interval

FORMATION: WILLIAMS FORK Status: PRODUCING Treatment Type:
Treatment Date: 02/04/2012 End Date: Date of First Production this formation: 02/23/2012
Perforations Top: 4640 Bottom: 7655 No. Holes: 300 Hole size: 0.42

Provide a brief summary of the formation treatment:

Open Hole: ☐

Stages 1-10 treated with a total of: 183,860 bbls of Slickwater.

This formation is commingled with another formation: ☐ Yes ☒ No

Total fluid used in treatment (bbl):

Max pressure during treatment (psi):

Total gas used in treatment (mcf):

Fluid density at initial fracture (lbs/gal):

Type of gas used in treatment:

Number of staged intervals:

Total acid used in treatment (bbl):

Max frac gradient (psi/ft):

Recycled water used in treatment (bbl):

Flowback volume recovered (bbl):

Fresh water used in treatment (bbl):

Disposition method for flowback:

Total proppant used (lbs):

Rule 805 green completion techniques were utilized: ☐

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 02/29/2012 Hours: 24 Bbl oil: 0 Mcf Gas: 1172 Bbl H2O: 135
Calculated 24 hour rate: Bbl oil: 0 Mcf Gas: 1172 Bbl H2O: 135 GOR: 0
Test Method: Flowing Casing PSI: 931 Tubing PSI: Choke Size: 46/64
Gas Disposition: SOLD Gas Type: DRY Btu Gas: 1170 API Gravity Oil: 0
Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth:

Reason for Non-Production:

Date formation Abandoned: Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt

Bridge Plug Depth: Sacks cement on top:

Comment:

Tubing not landed on this well. Encana will land tubing in 2012 a new 5A will be submitted.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Marina Ayala

Title: Permitting Technician Date: 3/22/2012 Email marina.ayala@encana.com
:

Attachment Check List

Att Doc Num	Name
400264170	FORM 5A SUBMITTED
400264176	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group **Comment** **Comment Date**

--	--	--

Total: 0 comment(s)