

FORM
5A

Rev
06/12

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400266568

Date Received:

03/29/2012

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 16700
2. Name of Operator: CHEVRON USA INC
3. Address: 6001 BOLLINGER CANYON RD
City: SAN RAMON State: CA Zip: 94583
4. Contact Name: DIANE PETERSON
Phone: (970) 675-3842
Fax: (970) 675-3800

5. API Number 05-103-05699-00
6. County: RIO BLANCO
7. Well Name: MCLAUGHLIN
Well Number: 28
8. Location: QtrQtr: SWSW Section: 23 Township: 2N Range: 103W Meridian: 6
9. Field Name: RANGELY Field Code: 72370

Completed Interval

FORMATION: WEBER Status: SHUT IN Treatment Type:

Treatment Date: 07/13/2001 End Date: Date of First Production this formation:

Perforations Top: 6210 Bottom: 6715 No. Holes: Hole size:

Provide a brief summary of the formation treatment: Open Hole: ☒

FRACTURE STIMULATE, CLEAN OUT AND STABILIZE OPEN HOLE TO 6590'

This formation is commingled with another formation: ☐ Yes ☒ No

Total fluid used in treatment (bbl): Max pressure during treatment (psi):

Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal):

Type of gas used in treatment: Number of staged intervals:

Total acid used in treatment (bbl): Max frac gradient (psi/ft):

Recycled water used in treatment (bbl): Flowback volume recovered (bbl):

Fresh water used in treatment (bbl): Disposition method for flowback:

Total proppant used (lbs): Rule 805 green completion techniques were utilized: ☐

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: Hours: Bbl oil: Mcf Gas: Bbl H2O:

Calculated 24 hour rate: Bbl oil: Mcf Gas: Bbl H2O: GOR:

Test Method: Casing PSI: Tubing PSI: Choke Size:

Gas Disposition: Gas Type: Btu Gas: API Gravity Oil:

Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth:

Reason for Non-Production: SHUT IN FOR FLOWLINE REPLACEMENT

Date formation Abandoned: Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt

Bridge Plug Depth: Sacks cement on top:

Comment:

FRACTURE STIMULATION AND NEW PBD OF 6590' REPORTED FOR 7/13/2001
CURRENT STATUS OF WELL SHUT IN DUE TO FLOWLINE REPLACEMENT 2/13/2012

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: DIANE L PETERSON

Title: REGULATORY SPECIALIST Date: 3/29/2012 Email DLPE@CHEVRON.COM
:

Attachment Check List

Att Doc Num	Name
400266568	FORM 5A SUBMITTED

Total Attach: 1 Files

General Comments

User Group **Comment** **Comment Date**

--	--	--

Total: 0 comment(s)