

FORM 5A

Rev 06/12

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with columns DE, ET, OE, ES

Document Number: 400268489

Date Received: 04/04/2012

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 100185
2. Name of Operator: ENCANA OIL & GAS (USA) INC
3. Address: 370 17TH ST STE 1700 City: DENVER State: CO Zip: 80202-
4. Contact Name: Marina Ayala Phone: (720) 876-5905 Fax: (720) 876-6905

5. API Number 05-045-19118-00
6. County: GARFIELD
7. Well Name: Story Gulch Unit Well Number: 8507D-36 B36496
8. Location: QtrQtr: Lot 2 Section: 36 Township: 4S Range: 96W Meridian: 6
9. Field Name: GRAND VALLEY Field Code: 31290

Completed Interval

FORMATION: WILLIAMS FORK Status: PRODUCING Treatment Type:

Treatment Date: 02/20/2012 End Date: Date of First Production this formation: 03/03/2012

Perforations Top: 8378 Bottom: 12019 No. Holes: 330 Hole size: 0.42

Provide a brief summary of the formation treatment: Open Hole: []

Stages 1-11 treated with a total of: 84,210 bbls of Slickwater.

This formation is commingled with another formation: [] Yes [X] No

Total fluid used in treatment (bbl): Max pressure during treatment (psi):
Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal):
Type of gas used in treatment: Number of staged intervals:
Total acid used in treatment (bbl): Max frac gradient (psi/ft):
Recycled water used in treatment (bbl): Flowback volume recovered (bbl):
Fresh water used in treatment (bbl): Disposition method for flowback:
Total proppant used (lbs): Rule 805 green completion techniques were utilized: []

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 03/09/2012 Hours: 24 Bbl oil: 0 Mcf Gas: 1796 Bbl H2O: 194

Calculated 24 hour rate: Bbl oil: 0 Mcf Gas: 1796 Bbl H2O: 194 GOR: 0

Test Method: Flowing Casing PSI: 1092 Tubing PSI: Choke Size: 44/64

Gas Disposition: SOLD Gas Type: DRY Btu Gas: 1170 API Gravity Oil: 0

Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth:

Reason for Non-Production:

Date formation Abandoned: Squeeze: [] Yes [] No If yes, number of sacks cmt

Bridge Plug Depth: Sacks cement on top:

Comment:

Tubing has not been landed on this well. Encana will land tubing in 2012, a new 5A will be submitted.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Marina Ayala

Title: Permitting Technician Date: 4/4/2012 Email marina.ayala@encana.com
:

Attachment Check List

Att Doc Num	Name
400268489	FORM 5A SUBMITTED
400268506	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group **Comment** **Comment Date**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)