

1. Red

728-07

2-25-12

14 6615 Slavery To The P.T

Left with 250 SKS 22 02 Dye, 16 Q's RCL

AV9. Cement 4.94 bbls/m

Used 50% Excess = 350 SKs, 79.16 lbs/s Slurry

Bump Plug 480 Psi at 337mm Float Collar Held

42.4665 34085, 3.379m 1.0655/m

4066/5, 34085, 3:36pm 1.0665/m

30665 400 PSI 3:30 AM 70665/mj

20665 320 PSI 3:32 PM 70665/m

10.66/s 200 PSI 3:30 AM 70.66/s/m

Drop Plug 3:27am, Displace 3:28am

DESCRIPTION OF JOB EVENTS	TIME
Safety Meeting	2:15 am
CIR	3:00 am
Cement	3:07 am to 3:23 am

JOBS SUMMARY

Wait 5 min then bleed off P₃, Wash up P₃ down, we have 6005Ks, 322 Dye, 2095 KCL,

Out Talks to Company Man, Deep Flg, Displace 42.4 bbls H₂O, Bump Plug at 150 Psi, over Lift Psi

Mixt Pump Tell Oye is seen then pump tub only At 15.2 lbs 12.7 yield Don't go over 30% excess with

INSTRUCTIONS PRIOR TO JOB: Rigup, Safety Meeting, Per Company Man, Lic 40665 H² with KCL & Dye x 10 in 27/10665.

[illegible]

CHARGE TO	Noble	OWNER	
MAILING ADDRESS		OPERATOR	Noble
CITY		CONTRACTOR	Ensign Rig 126
STATE ZIP CODE		DISTANCE TO LOCATION	
TIME ARRIVED ON LOCATION	10:20 pm.	TIME LEFT LOCATION	4:30 am
WELL DATA		PRESSURE LIMITATIONS	

DATE	WELL NAME	SECTION	TWP	RGE	COUNTY	FORMATION
2-25-12	DONOVAN D 02-30	34	4N	64W	Weld	

TREATMENT REPORT

FOREMAN Calvin Reimers

LOCATION WCR 57+40

REF. INVOICE # 10111

BISON OIL WELL CEMENTING, INC.

1738 Wynkoop St., Ste. 102
Denver, Colorado 80202
Phone: 303-296-3010
Fax: 303-298-8143
E-mail: bisono11@qwestoffice.net

