

FORM  
42

Rev  
03/12

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

09/01/2012

Document Number:

400323066

NOTICE OF NOTIFICATION

Entity Information

OGCC Operator Number: 100185 Contact Person: Roy Hunt  
Company Name: ENCANA OIL & GAS (USA) INC Phone: (985) 373-6566  
Address: 370 17TH ST STE 1700 Fax: ( )  
City: DENVER State: CO Zip: 80202-5632 Email: roy\_hunt@bellsouth.net  
API #: 05 - 013 - 06599 - 00 Facility ID: \_\_\_\_\_ Location ID: \_\_\_\_\_  
Facility Name: DEASON 4-2-36  
Sec: 36 Twp: 2N Range: 69W QtrQtr: NENW Lat: 40.100110 Long: -105.067450

SIGNIFICANT LOST CIRCULATION – Notify within 24 hours. report mud losses in excess of 100 barrels which require shutdown of operations for an hour or longer to pump lost circulation material and rebuild pit volume

Date of Lost Circulation: 08/31/2012 Time: 22:00 (HH:MM)  
Measure Depth: 7465 (feet) Mud Volume Lost: 1140 (bbl)  
Significant Kick Ensued? No

A Form 23 (Well Control Report) is required for Significant Kicks within 15 days. A significant kick shall be defined as one that is managed by shutting in the well to circulate out the kick or that is managed by going on choke and requiring an increase in mud weight exceeding 3/10ths of one pound per gallon to control.

This form must be signed by an authorized agent of the entity making assertion.

I certify under penalty of perjury that this report has been examined by me and to the best of my knowledge is true, correct and complete.

Print Name: Roy Hunt Email: roy\_hunt@bellsouth.net  
Signature: Roy Hunt Title: Well Site Supervisor Date: 09/01/2012