

FORM  
6Rev  
12/05State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

2237799

Date Received:

10/29/2012

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 41050

Contact Name: ARON RASCON

Name of Operator: HOMESTEAD OIL INC

Phone: (970) 8679007

Address: 16880 WILD PLUM CIRCLE

Fax: (970) 8678374

City: MORRISON State: CO Zip: 80465

Email: ARONRT@HOTMAIL.COM

For "Intent" 24 hour notice required,

Name: MONTOYA, JOHN

Tel: (970) 3974124

COGCC contact:

Email: john.montoya@state.co.us

API Number 05-123-16272-00

Well Name: BOULTER

Well Number: 15-24

Location: QtrQtr: SENW Section: 15 Township: 4N Range: 66W Meridian: 6

County: WELD

Federal, Indian or State Lease Number: 66637

Field Name: WATTENBERG

Field Number: 90750

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.313167

Longitude: -104.766433

GPS Data:

Date of Measurement: 06/12/2012

PDOP Reading: 1.8

GPS Instrument Operator's Name: Dinosaur Prod

Reason for Abandonment: ☐ Dry☒ Production for Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☒ Yes☐ No

Estimated Depth:

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☒ Yes☐ No

If yes, explain details below

Details: POSSIBLE HOLE DISCOVERED 8/24/12 NO OTHER DETAILS KNOWN

## Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7236	7247			
NIOBRARA	6918	7130			

Total: 2 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	386	150	386	0	CALC
1ST	7+7/8	4+1/2	12.6	7,388	420	7,388	6,658	CBL
S.C. 1.1	7+7/8	4+1/2	12.6	4,650	420	4,650	3,820	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6860 with 2 sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set 40 sks cmt from 3850 ft. to 3750 ft. Plug Type: STUB PLUG Plug Tagged: ☒  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
(Cast Iron Cement Retainer Depth)

Set 60 sacks half in. half out surface casing from 440 ft. to 280 ft. Plug Tagged: ☒

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing

Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No

\*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: PHILLIP WRIGHT

Title: MANAGER

Date: 10/23/2012

Email: PPPHILLIP@AOL.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: HOLLINSHEAD, RYAN

Date: 11/9/2012

### CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 5/8/2013

- 1) Provide 48 hour notice of MIRU to John Montoya at (970) 397-4124.
- 2) Provide an "As Plugged" wellbore diagram identifying the specific plugging completed.
- 3) Cut and pull casing above the top of cement. Cement plug across casing stub from 3850' to 3750' assumes that the casing is cut off at 3800'. Adjust depths for this plug, as necessary, depending on the actual depth of the casing stub. For this plug: pump plug and displace, shut in, WOC 4 hours and tag plug.
- 4) For the surface casing shoe plug, if not circulated to surface, tag plug, it must be at least 336' or higher, and a surface plug must be provided.
- 5) If unable to pull casing contact COGCC for plugging modifications.
- 6) Properly abandon flowlines as per Rule 1103.
- 7) See plugging changes above.

### **Attachment Check List**

Att Doc Num	Name
2237799	FORM 6 INTENT SUBMITTED
2237800	WELLBORE DIAGRAM

Total Attach: 2 Files

### **General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>

Total: 0 comment(s)