



State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

RECEIVED
12/13/2012

ACCIDENT REPORT

As required by Rule 602.b.

Report taken by:

DESCRIPTION OF ACCIDENT (Please be as specific as possible)

Name of Operator: EnCana Oil & Gas
Date of Incident: 12/11/12
Type of Facility (well, tank battery, flow line, pit): Well pad
Well Name & Number: SG 8502C-35 D36 496
API Number: 05-045-20932-0000
Connect to Accident (land owner, royalty owner, etc.): EnCana Contractor

Location	
County: Garfield	
Field Name: D36	
QtrQtr: Lot 4	Section: 36
Township: 4S	Range: 96W
Meridian: 6th	

Provide a detailed description of the accident, problem, and cause (equipment failure, human error, etc.):

An employee from RLP Field Services cut his finger while he was checking a steam heater on the Cuttings Press. The RLP employee's finger was cut by a fan blade from the heater. There was a small opening in the back panel of the unit. The employee was feeling for heat and he ran his hand over the rear panel. As he pulled his hand across the panel, his right index finger went into the opening and the blade cut the tip of his finger.

Other Notifications

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact Person	Response
12/12/2012	COGCC	Shaun Kellerby	Sent by E-mail