



State
of
Colorado



Krabacher - DNR, Jay <jay.krabacher@state.co.us>

RECEIVED

JAN 07 2013

COGCC/Rifle Office

Encana CBL Deferment Request (Production Casing)--Shideler Fee 31-13CC

2 messages

Reynolds, Scott D. <Scott.Reynolds@encana.com>

Mon, Jan 7, 2013 at 1:54 PM

To: "Krabacher, Jay (Jay.Krabacher@state.co.us)" <Jay.Krabacher@state.co.us>

Cc: "King, Kevin" <Kevin.King@state.co.us>

Encana CBL Deferment Request (Production Casing)

Well Name:	Shideler Fee 31-13CC
API Number:	05-045-21737-00
Pad Name:	O31E
Casing Size	4-1/2" 11.6# S80 BTC
Casing Setting Depth	9,002 ft MD-RKB
Plug Bump Date:	01-02-2013
Plug Bump Time:	19:40 hrs
Top of MV:	5255 ft MD-RKB
Top of Gas:	7095 ft MD-RKB
Designed TOC:	4355 ft MD-RKB
Temp Log TOC:	5050 ft MD-RKB

Bradenhead Pressure Report

Time	Bradenhead Pressure
6 hours	0
12 hours	0
24 hours	0
48 hours	0

72 hours	0
----------	---



Comments:

Good returns throughout cement job. Floats held. Annulus Static.

Scott Reynolds

Drilling Engineer – South Piceance

Encana Oil & Gas (USA) Inc

O: 720.876.5255

C: 303.895.0445

F: 720.876.6255

scott.reynolds@encana.com

Take a closer look: www.encana.com

Please note: Encana offices are closed the first and third Friday of each month

This email communication and any files transmitted with it may contain confidential and or proprietary information and is provided for the use of the intended recipient only. Any review, retransmission or dissemination of this information by anyone other than the intended recipient is prohibited. If you receive this email in error, please contact the sender and delete this communication and any copies immediately. Thank you.

<http://www.encana.com>

 **C920-00010_ENCANA_SHIDELER_FEE_31-13CC_TEMP_LOG_Combined.PDF**
535K

Krabacher - DNR, Jay <jay.krabacher@state.co.us>
To: "Reynolds, Scott D." <Scott.Reynolds@encana.com>
Cc: "King, Kevin" <Kevin.King@state.co.us>

Tue, Jan 8, 2013 at 4:00 PM

Scott:

Encana can defer the CBL on this well. Do monitor the bradenhead pressure closely -- as I think the temp log TOC is not quite as high as reported, above.

Regards,

Jay Krabacher
N W Area Engineer
C O G C C

cosas son mas como son ahora que ellas siempre fueron