


RETTA J #1 BORE RECLAMATION DETAIL



Notes:

1. Only 8 $\frac{3}{4}$ " pilot hole was drilled before the drilling operation was halted.
2. Maximum depth of the pilot hole was 47 feet from the surface.
3. No conductor pipe set.
4. The well pilot hole was cemented with flowable fill on 4-25-2012.

Sheet 1 of 1

	<p>InfoMaption Inc. 1514 Banyan Dr. Fort Collins, CO 80521 Ph. 970.581.3131 www.infomaption.com</p>	OPERATOR: RANCHERS EXPLORATION PARTNERS		Date 4-25-2012	File Name. 120424 RIVER WEST-2 WELL PLAT.dwg
		SURFACE LOCATION: NW $\frac{1}{4}$ NW $\frac{1}{4}$ SEC. 24, T6N R68W		Field Data TRM	Project No. 120104
				Drawn TRM	Date 2-12-2013