

PROPOSED HORIZONTAL WELL(S)														
Well Name and Number		Surface Location		Well Name and Number		Surface Location		Well Name and Number		Surface Location				
Maier 1A 28H		Section 28 T2N R66W		Maier 1D 28H		Section 28 T2N R66W		Maier 4C 28H		Section 28 T2N R66W				
Maier 1B 28H		Section 28 T2N R66W		Maier 4A 28H		Section 28 T2N R66W		Maier 4D 28H		Section 28 T2N R66W				
Maier 1C 28H		Section 28 T2N R66W		Maier 4B 28H		Section 28 T2N R66W								
OFFSET WELL EVALUATIONS														
API #	Well Name	Shortest Distance to a Proposed HZ Well	Operator	Spud Date	Status	SC Setting Depth	Base of Fox Hills/Depth of Deepest Water Well	Historical Remedial Work to Provide Fox Hills Coverage	Objective Formation Top NIOBRARA	Top of Cement	Shallower Productive Hydrocarbon Zones Within 1 Mile	Ability to Monitor Bradenhead Pressure at Surface Casing Shoe	Remedial Cementing Form 4 or Plugging Form 6 NOI Previously Submitted	Comments/BMPs for Proposed
05-123-10026-0000	Diane 1	130'	ECA	08/10/1980	PR	761	845.00	-	7140	6930		Yes	No	
05-123-09820-0000	Ursula 1	270'	MERIT								Sussex	Yes	No	NBRR not penetrated.
05-123-21366-0000	Diane 33-28	50'	ECA	03/24/2003	PR	984	840.00	-	7213	6650		Yes	No	
05-123-09920-0000	Ursula 2	55'	MERIT								Sussex	Yes	No	NBRR not penetrated.
05-123-20798-0000	Diane 43-28	75'	ECA	03/03/2002	PR	1043	827.00	-	7200	6790		Yes	No	
05-123-19926-0000	Diane 44-28	235'	ECA	03/25/2000	PR	996	873.00	-	7156	6800		Yes	No	
05-123-35601-0000	Diane 6-4-28	315'	ECA	05/31/2012	PR	1001	859.00	-	7176	4084		Yes	No	
05-123-09915-0000	Angela 1	250'	MERIT								Sussex	Yes	No	NBRR not penetrated.
05-123-15126-0000	Angela 42-28	130'	MERIT								NIOBRARA	Yes	No	Will make sure offset Operator has adequate coverage
05-123-35602-0000	Diane 8-6-28	295'	ECA	05/24/2012	PR	1004	860.00	-	7142	4730		Yes	No	
05-123-09189-0000	Maier 1	30'	ECA	05/02/1977	PR	232	819.00	-	7140	XXX		Yes	No	Will need CBL
05-123-35605-0000	Maier 31-28	298'	ECA	07/06/2012	PR	917	805.00	-	7298	4620	-	Yes	No	
05-123-20760-0000	Maier 32-28	250'	ECA	07/24/2002	PR	1020	799.00	-	7134	6840		Yes	No	
05-123-23687-0000	McQueary 28-2	60'	KAUFFMAN								Sussex	Yes	No	NBRR not penetrated.
05-123-23829-0000	Elaine 43-28	30'	KAUFFMAN								Sussex	Yes	No	NBRR not penetrated.
05-123-20797-0000	Maier 41-28	130'	ECA	03/20/2002	PR	1038	843.00	-	7145	6785	-	Yes	No	
05-123-09427-0000	UPRR 50 C 1	440'	KAUFFMAN								Sussex	Yes	No	NBRR not penetrated.
05-123-35604-0000	Maier 4-2-28	158'	ECA	06/30/2012	PR	921	800.00	-	7001	4210		Yes	No	
05-123-35607-0000	Maier 4-4-28	170'	ECA	06/16/2012	PR	920	805.00	-	7230	4380		Yes	No	
05-123-10840-0000	Breckler 1	277'	MISSION OIL								Sussex	Yes	No	Will make sure offset Operator has adequate coverage
05-123-35606-0000	Maier 8-4-28	350'	ECA	06/23/2012	PR	919	803.00	-	7671	4700		Yes	No	