

FORM  
2

Rev  
12/05

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400392998

Date Received:

APPLICATION FOR PERMIT TO:

1. ☒ Drill, ☐ Deepen, ☐ Re-enter, ☐ Recomplete and Operate

2. TYPE OF WELL

OIL ☒ GAS ☐ COALBED ☐ OTHER \_\_\_\_\_  
SINGLE ZONE ☒ MULTIPLE ☐ COMMINGLE ☐

Refiling ☐

Sidetrack ☐

PluggingBond SuretyID

20130007

3. Name of Operator: EE3 LLC

4. COGCC Operator Number: 10450

5. Address: 4410 ARAPAHOE AVENUE #100

City: BOULDER State: CO Zip: 80303

6. Contact Name: CLAYTON DOKE Phone: (303)216-0703 Fax: (303)216-2139

Email: cdoke@iptengineers.com

7. Well Name: HEBRON Well Number: 2-07H ST

8. Unit Name (if appl): Unit Number:

9. Proposed Total Measured Depth: 11583

WELL LOCATION INFORMATION

10. QtrQtr: NWNE Sec: 7 Twp: 7N Rng: 80W Meridian: 6

Latitude: 40.598306 Longitude: -106.415469

Footage at Surface: 420 feet FNL/FSL FNL 2361 feet FEL/FWL FEL

11. Field Name: UNNAMED Field Number: 85251

12. Ground Elevation: 8130 13. County: JACKSON

14. GPS Data:

Date of Measurement: 11/21/2008 PDOP Reading: 0.8 Instrument Operator's Name: UINTAH ENGINEERING & LAND SURVEYING

15. If well is ☐ Directional ☒ Horizontal (highly deviated) submit deviated drilling plan.

Footage at Top of Prod Zone: FNL/FSL FEL/FWL Bottom Hole: FNL/FSL FEL/FWL  
897 FNL 2599 FEL 600 FSL 600 FWL  
Sec: 7 Twp: 7N Rng: 80W Sec: 7 Twp: 7N Rng: 80W

16. Is location in a high density area? (Rule 603b)? ☐ Yes ☒ No

17. Distance to the nearest building, public road, above ground utility or railroad: 1694 ft

18. Distance to nearest property line: 420 19. Distance to nearest well permitted/completed in the same formation(BHL): 7603 ft

20. LEASE, SPACING AND POOLING INFORMATION

Objective Formation(s)	Formation Code	Spacing Order Number(s)	Unit Acreage Assigned to Well	Unit Configuration (N/2, SE/4, etc.)
NIOBRARA	NBRR	531-2	628	ALL

21. Mineral Ownership: ☒ Fee ☐ State ☐ Federal ☐ Indian Lease #: \_\_\_\_\_

22. Surface Ownership: ☒ Fee ☐ State ☐ Federal ☐ Indian

23. Is the Surface Owner also the Mineral Owner? ☒ Yes ☐ No Surface Surety ID#:

23a. If 23 is Yes: Is the Surface Owner(s) signature on the lease? ☒ Yes ☐ No

23b. If 23 is No: ☐ Surface Owners Agreement Attached or ☐ \$25,000 Blanket Surface Bond ☐ \$2,000 Surface Bond ☐ \$5,000 Surface Bond

24. Using standard QtrQtr, Sec, Twp, Rng format enter entire mineral lease description upon which this proposed wellsite is located (attach separate sheet/map if you prefer):

Township 7 North, Range 80 West, 6th P.M., Section 7: Lots 1-4, E½ W½ and E½

25. Distance to Nearest Mineral Lease Line: 600 ft 26. Total Acres in Lease: 628

### DRILLING PLANS AND PROCEDURES

27. Is H2S anticipated? ☐ Yes ☒ No If Yes, attach contingency plan.

28. Will salt sections be encountered during drilling? ☐ Yes ☒ No

29. Will salt (>15,000 ppm TDS CL) or oil based muds be used during drilling? ☐ Yes ☒ No

30. If questions 28 or 29 are yes, is this location in a sensitive area (Rule 901.e)? ☐ Yes ☒ No

31. Mud disposal: ☒ Offsite ☐ Onsite

If 28, 29, or 30 are "Yes" a pit permit may be required.

Method: ☐ Land Farming ☐ Land Spreading ☐ Disposal Facility Other: Back fill and cover

Note: The use of an earthen pit for Recompletion fluids requires a pit permit (Rule 905b). If air/gas drilling, notify local fire officials.

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top
CONDUCTOR	20	16		0	60	60	60	0
SURF	12+1/4	9+5/8	36	0	1,000	405	1,000	0
1ST	8+3/4	7	23	0	7,421	676	7,421	3,000
1ST LINER	6+1/4	4+1/2	11.6	6619	11,583	518	11,583	6,619

32. BOP Equipment Type: ☒ Annular Preventer ☒ Double Ram ☐ Rotating Head ☐ None

33. Comments Distance cited in #17 is to a public road. The distance to the nearest building is 2790'. All documents were executed under the previous operator of record, but were transferred along with the acreage pursuant to the purchase agreement already on file with the state (Doc #: 400395635). This well is not listed as a re-file because the API is invalid. This well is a re-file of a well where the previous operator failed to file a Form 2 for the pilot hole. Cannot refile on an API that does not exist. API# will be 05-057-06499-01.

34. Location ID: 413754

35. Is this application in a Comprehensive Drilling Plan ? ☐ Yes ☒ No

36. Is this application part of submitted Oil and Gas Location Assessment ? ☒ Yes ☐ No

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: CLAYTON DOKE

Title: SENIOR ENGINEER Date: \_\_\_\_\_ Email: cdoke@iptengineers.com

Based on the information provided herein, this Application for Permit-to-Drill complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Director of COGCC Date: \_\_\_\_\_

API NUMBER

05

Permit Number: \_\_\_\_\_ Expiration Date: \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

All representations, stipulations and conditions of approval stated in the Form 2A for this location shall constitute representations, stipulations and conditions of approval for this Form 2 Permit-to-Drill and are enforceable to the same extent as all other representations, stipulations and conditions of approval stated in this Permit-to-Drill.

Date retrieval failed for the subreport 'IntPolicy\_MTO' located at: W:\Inetpub\Net\Reports\policy\_mto.rdl. Please check th

### Attachment Check List

Att Doc Num	Name
400410632	WELL LOCATION PLAT
400415944	DEVIATED DRILLING PLAN
400415966	DIRECTIONAL DATA

Total Attach: 3 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)

### BMP

<u>Type</u>	<u>Comment</u>

Total: 0 comment(s)