



864 20 Road, Unit A
Fruita, Colorado 81521
(970) 858-8550
FAX (970) 858-8155

P.O. Box 338
Ignacio, Colorado 81137
(970) 563-4000
FAX (970) 563-4116

May 28, 2013

Jean Marie and James A. Etzler (Surface Owner)
10238 HWY 172
Ignacio, CO 81137

RE: Maralex Resources, Mollie Corynne 33-7-2 #3C, Oil and Gas Location Assessment
COGCC Rule 306 – Surface Owner Consultation

Dear Mr. and Mrs. Etzler,

Maralex Resources, Inc. (the operator), intends to submit to COGCC an Application for Permit to Drill the Mollie Corynne 33-7-2 #3C well on your property. This application also requires an Oil and Gas Location Assessment to be filed. The operator is required to consult with the surface owner about the details of the drilling location, site, topsoil management and other facilities to be used for operations. This consultation is meant to allow you, the surface owner, to provide comments on your preferences for the timing and locations for the proposed well and associated facilities. Maralex plans to drill the new well on the existing location of the Mollie Corynne #2A well.

In place of consulting with the operator, you may sign a waiver that will also fulfill the requirement for the Oil and Gas Location Assessment. Your signatures, agreeing to the statement below, will serve as the required waiver.

Thank you for your cooperation in this matter.

Sincerely,

Maralex Resources, Inc.

A.M. O'Hare, P.E.
President

I hereby waive the requirement to consult and comment on the proposed Maralex Mollie Corynne 33-7-2 #3C well per COGCC rule 306a as outlined in the letter above.

Jean Marie Etzler 5-30-13 James A. Etzler 5-30-13
Jean Marie Etzler Date James A. Etzler Date