



Kerr-McGee Gathering, LLC  
635 North 7<sup>th</sup> Avenue  
Brighton, Colorado 80601  
303-659-5922  
Fax: 303-655-4380

June 3, 2013

Mr. Tim Bates  
Production Superintendent  
Kerr-McGee Gathering LLC  
635 North 7<sup>th</sup> Avenue  
Brighton, Colorado 80601

Re: Pigging System 400 Lateral Platte Valley Project  
Township 2 North, Range 68 West, 6<sup>th</sup> P.M.  
Sections 7,18,19  
Township 2 North, Range 69 West, 6<sup>th</sup> P.M.  
Sections 24,25,  
Weld County, Colorado  
Boulder County, Colorado

Dear Tim:


Kerr-McGee Gathering LLC ("Kerr-McGee") is working on a revision of the current system. This segment of pipeline needed both above ground and buried appurtenance modifications to be compatible with the rest of our gathering system.

We also removed a drip pot from an environmentally sensitive wetlands area. Should you have any additional concerns, please contact me at 303-340-6613. Thank you.

Very truly yours,

Kerr-McGee Gathering LLC

Fred Birdwell  
Fieldman IV



**This is a brief time line summary of the events that have occurred summarizing work that was conducted on the Ross G Unit #1 location as described by Mr. Dave Bale; surface landman:**

- 5/6/13- Commenced construction.
- 5/7/13- We were notified by e-mail of a concerned citizen (Rod Brueske) in an e-mail from Charley Dein. We met with Mr. Rob Alexander of Boulder County Open Space, surface owner of the launcher location and had invited Mr. Brueske to this meeting but he declined our offer.
- 5/9/13- Mrs. Brueske, at 10:15AM, had requested that our vacuum excavation truck cease operations because the noise was bothering her. I met with Rod and explained our operations and said we would install the above ground appurtenance. Rod mentioned that his family had become ill due to vapors on the battery site due to a vapor recovery unit that was the wrong size to handle the amount of vapors. I told Rod we would do our receiver installation on 5-30-13 after 9:00AM so his wife and children would be gone for the day.
- 5/16/13-Tie-in work done in areas 1, 2, 3 (identified on sketch on page 2). The abandoned areas (between area 1 and 2) were filled with nitrogen on 5-17-13.
- 5/20/13- Excavation was done in preparation for tie-in.
- 5/29/13-Line was taken down to zero psig. The vent points used were both over ½ mile from the Brueske residence and routed through our baffled truck mounted vent tank. No liquids from the pipeline were recovered during this operation. It started raining and work was postponed, line was put back in service. Jim Precup with the COGC called with the complaint. I talked to Wayne and he said to call Jeff Sweetin, our security officer about the complaint from Rod Brueske.
- 5/30/13- The line segment was de-pressurized at two points over 1 ½ miles from the Brueske residence, no liquid or vapor reported. Received a call from Rod Brueske about 6:30AM mentioning that a crew was on location. I explained we were having a safety meeting but no actual pipeline work would be started until after 9:00AM. I met him on location at about 8:45AM. The pig was run through the line and the launcher was installed without incident. Rod Brueske requested that we find out the VOC of the paint we were going to use on the above ground facility. I mentioned I would get back to him and am lining up a time with Rod when we can paint the above ground appurtenance when his wife and children are not home.
- Tie in was done for areas 4, 5,6,7,8 on 5-30-13.
- Backfilling was begun on 5-31-13.

- Backfilling was completed on 6-1-13 on areas 4, 5,6,7,8.