



YETTER WELL SERVICE, INC.

P.O. Box 1808 • Sterling, Colorado 80751-7808

Phone (970) 522-2885

Date 10-15-2013

COMPANY CORAL PRODUCTION

LEASE CHLITSTENSEN

WELL NO. B-1

RIG Cement equip.

COUNTY Washington

Work Ordered By: J. CRUMLEY

Job Description: P&A

| | | HOURS | TOTAL |
|---|------|-------|-------|
| <u>10-15-2013</u> Cement Bulk Truck: load 145 sx portland, deliver to location. Problems with well, return to yard. @ \$96.- | | 4 | \$ - |
| <u>10-17-2013</u> : Cement Bulk Truck: To location, Mix 40 sx 15# cement. Cement thru retainers. @ \$96.- | | 4 | |
| <u>10-18</u> Cement Bulk Truck: Mix 40 sx cement 15 1/2# with 2% chlorides, spot cement on top of esg stub @ 1130'. Mix 50 sx 15 1/2# cement 2% chlorides Pump 1/2 in - 1/2 out plug @ 360' | | 4 | |
| RODS | PUMP | SUBS | |
| TUBING | SUBS | OTHER | |
| Remarks: | | | |
| FURNISHED | | | |
| <u>10-17</u> Duplex pump for retainer squeeze cement blending unit. | | 2 | 100.- |
| UNIT CHARGE | | | |
| <u>Arvin YETTER</u> <u>J. RUFF</u> | | | |
| | | TAX | |
| | | TOTAL | \$ |