



YETTER WELL SERVICE, INC.

P.O. Box 1808 • Sterling, Colorado 80751-7808

Phone (970) 522-2885

Date 10-17-13

COMPANY Coral Production

LEASE Christianson WELL NO. B-1

RIG 9

COUNTY Washington

Work Ordered By: Jack C.

Job Description:

	HOURS	TOTAL
Travel to location, uncap well, rig up for tubing, run stinger on tubing out of derrick, tag up, sub up, sting-in, rig up pump, cement mixer and Washington Head with rubber. Establish rate thru retainer - 1 bpm @ 800psi. Mix 40sx cement to 15". Pump cement & displace. Sting out and spot 2 1/2 bbls cement on top of retainer. Pull 10'its, pump 2 bbls down tub. Pull and lay down tubing. N, D well head, break out well head. Dig out surface. Couldn't get ring out of surface head. Cut ring out, impact head. Strap bell nipple. Unload ass. and work it. Had 9" at 100,000# pull. Set up ass. logs. Shut down.	10	

RODS PUMP SUBS
TUBING SUBS OTHER

Remarks:

FURNISHED		\$
210 BBL Tank	per day	
75 BBL Flat Tank		
50 BBL Flat Tank		
Washington Head		
Portable welder		2

UNIT CHARGE		
Jason R.	10	
John d.	10	
Matt M	10	
Charles R.	10	

TAX

TOTAL

#