



STATE OF
COLORADO

Young - DNR, Rob <rob.young@state.co.us>

Form 2A review - Pope 18-17 Pad (doc no 400416288)

2 messages

Young - DNR, Rob <rob.young@state.co.us>
To: Susana Lara-Mesa <slaramesa@kpk.com>

Mon, Oct 28, 2013 at 1:04 PM

Hi Susi,

Can you confirm that the production from this well will be flowing to the Lewis 2-20 tank battery and that no additional disturbance will be needed at that location that would require a new Form 2A?

Thanks,

—
Robert J. Young
Oil and Gas Location Assessment Specialist
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80023
 [\(303\) 894-2100](tel:(303)894-2100) X 5144

Susana Lara-Mesa <SLaraMesa@kpk.com>
To: "Young - DNR, Rob" <rob.young@state.co.us>

Mon, Oct 28, 2013 at 1:44 PM

Hi Rob,

You're correct. This will not require any additional disturbance.

Susi

Susana Lara-Mesa | K.P. Kauffman Company, Inc.

1675 Broadway, Suite 2800 | Denver, CO 80202 | T: [\(303\) 825-4822](tel:(303)825-4822) | SLaraMesa@kpk.com | www.kpk.com

From: Young - DNR, Rob [mailto:rob.young@state.co.us]
Sent: Monday, October 28, 2013 1:05 PM
To: Susana Lara-Mesa
Subject: Form 2A review - Pope 18-17 Pad (doc no 400416288)

[Quoted text hidden]