

## WELLBORE DIAGRAM

**Well Name:** Monks A11-9S-56W-01

**API:** 05-073-06498

**Location:** SESE 11-9S-56W

**Field:** Brass Hat

**State:** Colorado

**County:** Lincoln

**Engineer:** BDB

**WBD:** MLL

**Date:** 11/4/2013

### Casing Design

**Surface:** 9 5/8" 36# J-55 LTC

**Production:** 5.5" 17# L80 LTC

### Cement Jobs

**Surface:** 175 Sks, cement to surface

**Production:** 856 sks cement

9 5/8" Shoe @ 515'

