



YETTER WELL SERVICE, INC.

P.O. Box 1808 • Sterling, Colorado 80751-7808

Phone (970) 522-2885

Date Aug 28, 2012

COMPANY WESTERN OPERATING

LEASE STUARDO STATE WELL NO. 1

RIG 9

COUNTY _____

Work Ordered By: JACK

Job Description:

			HOURS	TOTAL
<p>To location, continue working csg. csg wouldn't come free. Rig up T-W WIRELINE. Stand by while setting CIRP and dump bailer. Mix gel bentonite and fill csg. Shoot csg. off @ 1005'. Rig down T.W. Work csg @ 14000' to get csg free. Pull lay down 35 jts. Pick up 33 jts of tubing. Pump 40 sx cement plug 1/2 in - 1/2 out of csg stub. Pull tub up to 18 jts, mix & pump gel ben on top pill @ 100'. Pull tub up to 12 jts, mix & pump 35 sx cement @ 370. Pull tub out of hole, let cement plug set up. Haul sucker rods to sterling yard.</p>			12	
RODS	PUMP	SUBS		
TUBING	SUBS	OTHER		
Remarks:				
FURNISHED	14 sx gel (bentonite)	@ \$13.56		\$ 189.00
	3 1/2" csg tools - 1005 recovered.			436.00
	Csg tool truck To & From LOCATION		2	
UNIT CHARGE				
Austin Koch			12	3060.00
T. DEMACIA			12	
C. HIZMAIK			12	
ALAN YETTER				
Randy Barber.			12	
TAX				7.37
TOTAL				\$ 3692.37