

FORM 19
Rev 6/99

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303)894-2100 Fax:(303)894-2109



FOR OGCC USE ONLY

RECEIVED
9/26/2013

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation

Spill report taken by:

FACILITY ID:

OPERATOR INFORMATION

Name of Operator: <u>Kerr-McGee Oil & Gas Onshore LP</u> OGCC Operator No: <u>47120</u>	Phone Numbers
Address: <u>1099 18th Street, Suite 1800</u>	No: <u>720-929-6000</u>
City: <u>Denver</u> State: <u>CO</u> Zip: <u>80202</u>	Fax: <u>720-929-7726</u>
Contact Person: <u>Paul Schneider</u>	Email: <u>Paul.Schneider@anadarko.com</u>

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: <u>9/14/2013</u> Facility Name & No: <u>State of Colorado AM 1, State 16-11L, 16-12L, 16-14L, Houston State 22-16, Burchfield State 33-16,</u>	County: <u>Weld</u>
Type of Facility (well, tank battery, flow line, pit): <u>Production Facility</u>	QtrQtr: <u>NESW</u> Section: <u>16</u>
Well Name and Number: <u>State of Colorado AM 1</u>	Township: <u>3N</u> Range: <u>67W</u>
API Number: <u>05-123-09898</u>	Meridian: <u>6th</u>

Specify volume spilled and recovered for the following materials:

Oil spilled: 0.5 bbl Oil recov'd: 0 Water spilled: 1 bbl Water recov'd: 0 Other spilled: 0 Other recov'd: 0

Ground Water impacted? Yes No Unknown Surface Water impacted? Yes No

Contained within berm? Yes No Area and vertical extent of spill: Unknown

Current land use: Rangeland Weather conditions: 70° F, rain

Soil/geology description: Unknown

IF LESS THAN A MILE, report distance IN FEET to nearest ... Surface water: Floodwater present wetlands: 400 S buildings: 2,600 E

Livestock: Unknown Water wells: 3,218 E Depth to shallowest ground water: Unknown

Cause of spill (e.g. equipment failure, human error, etc.): Extreme Weather - Flood conditions along the St. Vrain Creek

Detailed description of the spill/release incident: While surveying the location on 9/16/2013 from a helicopter, it was observed that the produced water tank and load line drip bucket were overturned by flood water. Approximately 1 bbl of produced water and 0.5 bbl of condensate were released. The actual release volume will be determined when the floodwaters recede and the site can be safely accessed.

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered): The wells were remotely shut in. The site will be assessed for petroleum hydrocarbon impacts once the floodwaters recede.

Describe any emergency pits constructed: NA

How was the extent of contamination determined? A sampling and analysis plan will be developed once the floodwaters recede.

Further remediation activities proposed (attach separate sheet if needed): Will be provided on a Form 27.


Describe measures taken to prevent problem from reoccurring: Not applicable (weather/flooding).

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
9/16/2013	NRC	Ms. Johnson	800-424-8802	Report #1060369
9/16/2013	CDPHE	Spill Hotline	877-518-5608	Report #2013-0646
9/16/2013	Weld County	David Bauer	970-304-6496 ext 3739	Left voicemail
9/16/2013	Weld County	Roy Rudisill	By email	

Spill/Release Tracking No: **2146350**



STATE OF COLORADO AM 1,
 STATE 16-11L, 16-12L, 16-14L,
 HOUSTON STATE 22-16,
 BURCHFIELD STATE 33-16

IMAGE COURTESY OF USGS/ESRI

LEGEND

 SITE LOCATION




FIGURE 1
SITE LOCATION MAP
 STATE OF COLORADO AM 1, STATE 16-11L, 16-12L, 16-14L,
 HOUSTON STATE 22-16, BURCHFIELD STATE 33-16
 NESW SEC 16-T3N-R67W
 WELD COUNTY, COLORADO
 KERR-MCGEE OIL & GAS ONSHORE LP

