

WELLBORE DIAGRAM

Directions: WCR68 & WCR 59, 0.4 mile east on WCR 68, 0.5 mile S into location

Bayswater E & P

Larson Farms 5-24

NESW Sec 24-T6N-R64W
SHL: 2226' FSL, 2452' FWL
BHL: 1951' FSL, 1985' FEL
Weld County CO
05-123-34145

Updated
11/8/2013
SMS

