



February 4, 2014

Mr. Matt Lepore
Colorado Oil & Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203

Re: Request for Rule 317.o Exception (Open Hole Logging Requirements)

MCCONAHAY 4A-34H-P266	MCCONAHAY 1B-34H-H266
MCCONAHAY 4B-34H-P266	MCCONAHAY 1C-34H-H266
MCCONAHAY 4C-34H-P266	MCCONAHAY 1D-34H-H266
MCCONAHAY 4D-34H-P266	MCCONAHAY 1E-34H-H266
MCCONAHAY 4E-34H-P266	(Ref: McConahay 1A-34H)
(Ref: McConahay 44-34)	
Weld County, CO	

Dear Mr. Lepore:

Please let this letter serve as a request for a Rule 317.o Exception for the proposed wells listed above. Rule 317.o requires logging all wells with a minimum of a resistivity log with gamma ray to adequately describe the stratigraphy and open hole logs to adequately verify the setting depth of surface casing and aquifer coverage.

Encana has identified the **McConahay 1A-34H & McConahay 44-34** wells as being in close enough proximity and as having acceptable logs to adequately describe the stratigraphy of the wellbores of the wells proposed on this multi-well pad.

All these wells will have a cement bond log with gamma ray run from the intermediate casing shoe, or as close as possible, to above surface casing shoe to verify the setting depth of surface casing and aquifer coverage. satisfy the state's request.

The horizontal portion of the all these wells will be logged while drilling with a gamma ray tool.

Encana requests approval of an exception to not run any open-hole logs in the vertical and directional build portion and not run a resistivity log in the horizontal portion of these wells.

Encana will report and submit all logs run on the Form 5 for every well..

Thank you for your assistance in this matter. If you have any questions or comments, please contact me at 720-876-5586.

Sincerely,
ENCANA OIL & GAS (USA) INC.

A handwritten signature in blue ink that reads "Chris McRickard".

Chris McRickard
Permitting Analyst

Encana Oil & Gas (USA) Inc.

Republic Plaza
370 – 17 Street, Suite 1700
Denver, Colorado
United States 80202

t 303.623.2300

f 303.623.2400

www.encana.com