

FORM

19

Rev 6/99

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax: (303)894-2109



FOR OGCC USE ONLY

RECEIVED
2/6/2014

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

Spill report taken by:

 FACILITY ID:
 333963

OPERATOR INFORMATION

Name of Operator: <u>Maralex Resources, Inc.</u>	OGCC Operator No: <u>53255</u>	Phone Numbers
Address: <u>PO Box 338</u>		No: <u>970-563-4000</u>
City: <u>Ignacio</u>	State: <u>CO</u> Zip: <u>81137</u>	Fax: <u>970-563-4116</u>
Contact Person: <u>Naomi Azulai</u>		E-Mail: <u>naomi@maralexinc.com</u>

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: <u>1/27/2014</u>	Facility Name & No.: _____	County: <u>La Plata</u>
Type of Facility (well, tank battery, flow line, pit): <u>well</u>		QtrQtr: <u>NWSW</u> Section: <u>11</u>
Well Name and Number: <u>Keegan Patrick 33-7-11 2A</u>		Township: <u>33N</u> Range: <u>7W</u>
API Number: <u>05-067-09016</u>		Meridian: <u>6</u>

Specify volume spilled and recovered (in bbls) for the following materials:

Oil spilled: _____ Oil recov'd: _____ Water spilled: 1 bbl Water recov'd: _____ Other spilled: _____ Other recov'd: _____

Ground Water impacted? ☐ Yes ☒ No Surface Water impacted? ☐ Yes ☒ No

Contained within berm? ☐ Yes ☒ No Area and vertical extent of spill: 1" deep x 30sqft

Current land use: _____ Weather conditions: sunny and clear

Soil/geology description: zyme clay loam, 3 to 25 percent slopes

IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: 150 wetlands: _____ buildings: 600

Livestock: _____ water wells: 400 Depth to shallowest ground water: 140

Cause of spill (e.g., equipment failure, human error, etc.): Equipment leak Detailed description of the spill/release incident:

The polished rod liner was leaking due to wear and tear on the equipment. The polished rod is part of the mechanical equipment on the well and is not associated with any kind of pit or containment.

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):

The leak was fixed by repairing the polished rod liner.

Describe any emergency pits constructed:

No pits required.

How was the extent of contamination determined:

Visually.

Further remediation activities proposed (attach separate sheet if needed):

No further activities are proposed.

Describe measures taken to prevent problem from reoccurring:

Equipment fixed.

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
1/28/2014	COGCC	Alex Fischer	via email	resubmit form 19
2/6/2014	La Plata County	Courtney Roseberry	via email	-
2/6/2014	Surface Owner	Hilary and Matthew Paragin	970-563-0407	via fax (phone # gives fax tone)

Spill/Release Tracking No: 2147672

