

The Farr #1 Plug was set in order to prepare for the following frac jobs:

State North Platte 11-14-26HNB

State North Platte 11-14-26HC

State North Platte F-J-26HNB

State North Platte F-J-26HC

State North Platte F11-J14-26HNC

Please attach this form 42 to the above wells for documentation.

Thank you. Please contact Hannah Larsen at 720.440.6163 with any questions.