



STATE OF
COLORADO

Herbert - DNR, Rob <rob.herbert@state.co.us>

Returned to draft: DocNum 2361114

2 messages

Herbert - DNR, Rob <rob.herbert@state.co.us>
To: CENTRALOPERATING@aol.com

Mon, Feb 24, 2014 at 10:40 AM

Patty,

The subject 2A was returned to draft for the following deficiencies:

- Contact/Submitter is not a COGCC registered agent.
- The right to construct in the Surface & Minerals tab should be the oil and gas lease.
- The Cultural Setbacks tab is incomplete; please follow instructions to complete Cultural Distance Information.
- Water well sampling Rule should be 609 in the Water Resources tab.
- Missing attached Location Pictures required by Rule 303.b.(3)B.
- Missing attached NRCS Map Unit descriptions required by Rule 303.b.(3)H.

Thanks for your attention to this matter.

Rob Herbert, P.G.
Permit/Completion Technician
Colorado Oil and Gas Conservation Commission
Phone: (303) 894-2100 Ext. 5130
E-mail: Rob.Herbert@state.co.us

Davewinslow1@cs.com <Davewinslow1@cs.com>
To: Centraloperating@aol.com, Rob.Herbert@state.co.us

Tue, Feb 25, 2014 at 2:25 PM

Rob,

Attached are all the documents on the #1 William Miller well. I have added the things that you asked for.

Patty Brew - President of Central Operating - is signing Form 1 and you should have that within a day or two.

I have also modified the Forms 2 and 2A on the Friedly 1B well and will send them to you in a separate email.

Give me a call if you have any other concerns.

Rgds,

David G. Winslow

Petroleum Engineer
Winslow Resources, Inc.
2840 Berry Lane
Golden, CO 80401
(303) 279-1629
Fax (303) 279-8430
Cell (303) 919-8847
Home (303) 232-6525

*E*Mail: davewinslow1@cs.com

In a message dated 2/25/2014 9:59:19 AM Mountain Standard Time, Centraloperating@aol.com writes:

Subj:Fwd: Returned to draft: DocNum 2361114
Date:2/25/2014 9:59:19 AM Mountain Standard Time
From:Centraloperating@aol.com
To:davewinslow1@cs.com, donandeun@cs.com
Received from Internet:

Heather LM Vasina

CENTRAL OPERATING, INC.
1600 Broadway Suite 1050
Denver, CO 80202
(303)894-9576

From: rob.herbert@state.co.us
To: CENTRALOPERATING@AOL.COM
Sent: 2/24/2014 10:40:26 A.M. Mountain Standard Time
Subj: Returned to draft: DocNum 2361114

Patty,

The subject 2A was returned to draft for the following deficiencies:

Contact/Submitter is not a COGCC registered agent.
The right to construct in the Surface & Minerals tab should be the oil and gas lease.
The Cultural Setbacks tab is incomplete; please follow instructions to complete Cultural Distance Information.
Water well sampling Rule should be 609 in the Water Resources tab.
Missing attached Location Pictures required by Rule 303.b.(3)B.
Missing attached NRCS Map Unit descriptions required by Rule 303.b.(3)H. Thanks for your attention to this matter.

Rob Herbert, P.G. Permit/Completion Technician
Colorado Oil and Gas Conservation Commission
Phone: (303) 894-2100 Ext. 5130
E-mail: Rob.Herbert@state.co.us



#1 WILLIAM MILLER ACCE00.ZIP

9970K