

WELLBORE DIAGRAM

Directions: 18th St and Cherry St (Greeley) SE into

Bayswater E & P Kuettel CNW-15

SWSW Sec 10-T5N-R65W
SHL: 417' FSL, 1041' FWL
BHL: 1189' FNL, 1326' FWL
Weld County CO
05-123-23880

Updated
11/14/2013
BCB

