

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400604100

Date Received:

05/07/2014

Spill report taken by:

Spencer, Stan

Spill/Release Point ID:

437117

## SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: CHEVRON PRODUCTION COMPANY OGCC Operator No: 16700Address: 100 CHEVRON RDCity: RANGELY State: CO Zip: 81648Contact Person: Tammie Lee Crossen**Phone Numbers**Phone: (970) 675-3705Mobile: (970) 675-3800Email: tvzf@chevron.com

### INITIAL SPILL/RELEASE REPORT

Initial Report Date: 05/07/2014 Date of Discovery: 05/05/2014 Spill Type: Recent Spill**Spill/Release Point Location:**Location of Spill/Release: QTRQTR NWNE SEC 36 TWP 2N RNG 102W MERIDIAN 6Latitude: 40.105100 Longitude: -108.789160Municipality (if within municipal boundaries): \_\_\_\_\_ County: RIO BLANCO**Reference Location:**Facility Type: WELL ☒ Well API No. (if the reference facility is well) 05-103-06306☐ Facility ID (if not a well) \_\_\_\_\_☐ No Existing Facility ID**Fluid(s) Spilled/Released (please answer Yes/No):**Was one (1) barrel or more spilled outside of berms or secondary containment? NoWere Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): >=20 and <50Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0Specify: 30 bbls were spilled**Land Use:**Current Land Use: NON-CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: 80 degrees and partly cloudySurface Owner: STATE

Other(Specify): \_\_\_\_\_

**Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):**Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On Monday (05-05-2014) at approximately 4:30 PM a water leak occurred on a 3" injection line, coated spool, at Weyrauch 2-36. Approximately 30 BBLs of brine water and 0 BBLs of oil were released. The line was shut in immediately upon detection. Vacuum trucks removed all of the free fluid; estimated recovery was approximately 29 BBLs of brine water and 0 BBLs of oil were recovered. The fluids that were picked up were taken to the truck unloading facility at the Main Water Plant for recycling. The affected was water washed and soil samples will be taken.

COGCC Comment Only:

List Agencies and Other Parties Notified:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Tammie Lee Crossen

Title: HE Specialist Date: 05/07/2014 Email: tvzf@chevron.com

### **Attachment Check List**

<b><u>Att Doc Num</u></b>	<b><u>Name</u></b>
400604100	FORM 19 SUBMITTED
400604111	TOPOGRAPHIC MAP

Total Attach: 2 Files