

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 100185 Contact Name: AMY HENLINE
 Name of Operator: ENCANA OIL & GAS (USA) INC Phone: (720) 876-3364
 Address: 370 17TH ST STE 1700 Fax: _____
 City: DENVER State: CO Zip: 80202- Email: AMY.HENLINE@ENCANA.COM

For "Intent" 24 hour notice required, Name: LONGWORTH, MIKE Tel: (970) 812-7644
 COGCC contact: Email: mike.longworth@state.co.us

API Number 05-045-11051-00 Well Number: WF13D N23 596
 Well Name: N. PARACHUTE
 Location: QtrQtr: SESW Section: 23 Township: 5S Range: 96W Meridian: 6
 County: GARFIELD Federal, Indian or State Lease Number: _____
 Field Name: GRAND VALLEY Field Number: 31290

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.595851 Longitude: -108.136898
 GPS Data:
 Date of Measurement: 02/22/2007 PDOP Reading: 4.4 GPS Instrument Operator's Name: BEN JOHNSON
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	24	16	42	92	6	90	0	CALC
SURF	12+1/4	9+5/8	36	2,500	1,055	2,508	0	CALC
1ST	7+7/8	4+1/2	11.6	9,117	1,415	9,127	2,760	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 2550 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 5394 ft. with 90 sacks. Leave at least 100 ft. in casing 5394 CICR Depth
 Perforate and squeeze at 2550 ft. with 45 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 (Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Encana requests approval to plug & abandon the subject well. Please see the attached proposed plugging procedures and wellbore diagrams (current & proposed).

Contact Information:
 Lannie Massey
 P&A Field Coordinator
 Encana Services Company Ltd.
 970-675-4477 (office)
 970-629-8733 (cell)
 lannie.massey@encana.com

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: AMY HENLINE
 Title: REGULATORY ANALYST Date: _____ Email: AMY.HENLINE@ENCANA.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400611292	WELLBORE DIAGRAM
400611293	WELLBORE DIAGRAM
400611294	PROPOSED PLUGGING PROCEDURE

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)