

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found.
Step 2. Sample now, if intermediate or surface casing pressure >25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test.
Step 4. Conduct intermediate casing test.
Step 5. Send report to BLM within 30 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: 10084
2. Name of Operator: Pioneer Natural Resources
3. BLM Lease No: N/A
4. API Number: 05-071-04008
5. Multiple completion? ☐ Yes ☒ No
6. Well Name: Wood Number: 43-2V
7. Location (QtrQtr, Sec, Twp, Rng, Meridian): NE 1/4 Sec 2-38 S 66 W
8. County: Las Animas
9. Field Name: Purgatoire River
10. Minerals: ☒ Fee ☐ State ☐ Federal ☐ Indian

11. Date of Test: 10/20/11
12. Well Status: ☐ Flowing ☐ Shut In
☐ Gas Lift ☒ Pumping ☐ Injection
☐ Clock/Intermittent ☐ Plunger Lift
13. Number of Casing Stungs: ☒ Two ☐ Three ☐ Liner?

14. STEP 1: EXISTING PRESSURES
Record all pressures as found
Tubing: Fm: 15
Tubing: Fm: 18.74
Prod. Casing: Intermediate Csg: Surface Casing: 0

15. STEP 2: See instructions above.

16. STEP 3: BRADENHEAD TEST

Buried valve? ☐ Yes ☒ No Confirmed open? ☒ Yes ☐ No

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below:
O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H₂O; M = Mud; W = Whisper; S = Surge; G = Gas

Elapsed Time (Min Sec)	Fm: Tubing	Fm: Tubing	Production Casing PSIG	Intermediate Casing PSIG	Bradenhead Flow
00:	15		18.74		0
05:					
10:					
15:					
20:					
25:					
30:					

BRADENHEAD SAMPLE TAKEN?
☐ Yes ☒ No ☐ Gas ☐ Liquid

Character of Bradenhead fluid: ☐ Clear ☐ Fresh
☐ Sulfur ☐ Salty ☐ Black
☐ Other: (describe)

Sample cylinder number:

Note instantaneous Bradenhead PSIG at end of test: >

17. STEP 4: INTERMEDIATE CASING TEST

Buried valve? ☐ Yes ☐ No Confirmed open? ☐ Yes ☐ No

With gauges monitoring production casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below:
O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H₂O; M = Mud; W = Whisper; S = Surge; G = Gas

Elapsed Time (Min Sec)	Fm: Tubing	Fm: Tubing	Production Casing PSIG	Intermediate Casing PSIG	Intermediate Flow
00:					7523
05:					6985
10:					6646
15:					
20:					
25:					
30:					

INTERMEDIATE SAMPLE TAKEN?
☐ Yes ☐ No ☐ Gas ☐ Liquid

Character of Intermediate fluid: ☐ Clear ☐ Fresh
☐ Sulfur ☐ Salty ☐ Black
☐ Other: (describe)

Sample cylinder number:

Note instantaneous Intermediate Casing PSIG at end of test: >

18. Comments: Well going to gathering

19. STEP 5: See instructions above.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed by: David A. Bie Title: Lease Operator II Phone: 719-896-7898

Signed: [Signature] Title: _____ Date: 10/20/11

WITNESSED BY: _____ Title: _____ Agency: _____