

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 400666025			
Date Received:			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>100185</u>	Contact Name: <u>AMY HENLINE</u>
Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u>	Phone: <u>(720) 876-3364</u>
Address: <u>370 17TH ST STE 1700</u>	Fax: _____
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>	Email: <u>AMY.HENLINE@ENCANA.COM</u>
For "Intent" 24 hour notice required, Name: <u>Longworth, Mike</u> Tel: <u>(970) 812-7644</u>	
COGCC contact: Email: <u>mike.longworth@state.co.us</u>	

API Number <u>05-045-15547-00</u>	Well Number: <u>EF05A-20 C29 59</u>
Well Name: <u>N. PARACHUTE</u>	
Location: QtrQtr: <u>NENW</u> Section: <u>29</u> Township: <u>5S</u> Range: <u>95W</u> Meridian: <u>6</u>	
County: <u>GARFIELD</u> Federal, Indian or State Lease Number: _____	
Field Name: <u>WILDCAT</u> Field Number: <u>99999</u>	

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.590293 Longitude: -108.079856

GPS Data:
Date of Measurement: 09/24/2013 PDOP Reading: 2.7 GPS Instrument Operator's Name: Brandon Birdsall

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	30	20	55	160	500	160	0	VISU
SURF	12+1/4	9+5/8	36	2,808	629	2,808	0	VISU

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 80 sks cmt from 2808 ft. to 2608 ft. Plug Type: CASING Plug Tagged:
Set 80 sks cmt from 200 ft. to 0 ft. Plug Type: CASING Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
Set _____ sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
*Wireline Contractor: _____ *Cementing Contractor: _____
Type of Cement and Additives Used: _____
Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Encana requests approval to plug & abandon the subject well. Please see the attached proposed plugging procedures and wellbore diagrams (current & proposed).

Contact Information:
Lannie Massey
P&A Field Coordinator
Encana Services Company Ltd.
970-675-4477 (office)
970-629-8733 (cell)
lannie.massey@encana.com

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: AMY HENLINE
Title: REGULATORY ANALYST Date: _____ Email: AMY.HENLINE@ENCANA.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400666029	FORM 6 INTENT SUBMITTED
400666030	PROPOSED PLUGGING PROCEDURE
400666031	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)