



STATE OF  
COLORADO

Andrews - DNR, Doug <doug.andrews@state.co.us>

---

## COGCC Form 2A review of Extraction's WAAG MIDDLE SENW PAD #1 LOCATION - Doc #400647900

2 messages

---

**Andrews - DNR, Doug** <doug.andrews@state.co.us>  
To: Nick Curran <nick.curran@iptenergyservices.com>

Mon, Sep 22, 2014 at 1:17 PM

Nick,

I have reviewed the referenced Form 2A Oil & Gas Location Assessment and have the following comments.

1) Due to the proximity of irrigation ditches to this proposed oil and gas location, I will change the Sensitive Area designation from NO to YES in the Water Resources section.

2) Due to the proximity of irrigation ditches, I will place the following Condition of Approval on this Form 2A: "Operator must implement site-specific best management practices in accordance with good engineering practices, including, but not limited to, construction of a berm or diversion dike, site grading, or other comparable measures, sufficient to protect the irrigation ditches located 24 feet north and 206 feet northeast of the oil and gas location from a release of drilling, completion, produced fluids, and chemical products."

3) You have included a comment that indicates the well pad will flow back (produce) to the WAAG SOUTH SESW PAD #1 (Doc #400658921). However, in the Related Remote Locations section you have indicated these wells will produce to the WAAG NORTH NENW PAD #1 (Doc #400658916). Please confirm where Extraction intends to produce these well too and I will change the Form 2A to reflect that.

Please respond to this correspondence by October 22, 2014. If you have any questions, please contact me. Thank you.

--

*Doug Andrews*

Oil & Gas Location Assessment Specialist - Northeast Area



1120 Lincoln St., Suite 801  
Denver, CO 80203  
[doug.andrews@state.co.us](mailto:doug.andrews@state.co.us)  
303-894-2100 Ext. 5180

---

**Nick Curran** <Nick.Curran@iptenergyservices.com>  
To: "Andrews - DNR, Doug" <doug.andrews@state.co.us>

Mon, Sep 22, 2014 at 1:25 PM

Hi Doug,

Thanks for the heads up on the typo about where the Middle Waag Pad flows back to. I apologize. That middle pad does indeed flow back to the WAAG SOUTH SESW PAD #1 (Doc #400658921).

I am ok the other changes you proposed. Thanks again,

Nick

**From:** Andrews - DNR, Doug [mailto:[doug.andrews@state.co.us](mailto:doug.andrews@state.co.us)]

**Sent:** Monday, September 22, 2014 1:17 PM

**To:** Nick Curran

**Subject:** COGCC Form 2A review of Extraction's WAAG MIDDLE SENW PAD #1 LOCATION - Doc #400647900

[Quoted text hidden]

---

The information contained in this e-mail message (and its attachments) may be privileged, confidential and protected from disclosure. If you are not the intended recipient, please do not read, copy, use, or disclose this communication to others. If you think that you have received this e-mail message in error, please immediately e-mail the sender, then delete this message and any "reply" response from your system. This electronic mail transmission is not intended (and may not be construed or deemed for any purpose) to contain or be an electronic signature.

---