



Noble Energy, Inc. Waste Management Plans Summary

The following describes Noble Energy, Inc.'s (Noble) general plan for proper handling and disposal of Exploration and Production (E&P) waste, including produced water, drill mud, and cuttings and tank bottoms.

- E&P waste will be stored onsite in compatible containers, e.g. frac tanks, three sided tanks, bermed areas, etc. Containers will be inspected on a regular basis to ensure they are in good condition and free of severe rust, bulging and/or structural defects.
- E&P wastes will be transported offsite by a licensed transporter via truck. Truck transport frequency will vary from site to site based on waste volumes.
- E&P petroleum impacted soils, drill cuttings, and drill mud will be disposed of at licensed third party disposal facilities (landfills). Tank bottoms will be disposed of at E&P licensed third party disposal facilities (landfills). Liquid wastes, including flowback and produced water will be disposed of at licensed third party injection facilities.
 - Third Party Disposal Facilities
 - Waste Management
 - Buffalo Ridge Landfill
 - North Weld County Landfill
 - Denver Regional Landfill
 - Allied Waste
 - Tower Landfill
 - Third Party Injection Facilities
 - High Sierra Injection Facilities
- Per Colorado Oil and Gas Conservation Commission (COGCC) Rule 907.a.(3), Reuse and Recycling of E&P waste, Noble with prior approval from the COGCC will potentially recycle and reuse produced water/flowback to be used in downhole frac operations.

- Per Colorado Oil and Gas Conservation Commission (COGCC) Rule 907.a.(3), Reuse and Recycling of E&P waste, Noble with prior approval from the COGCC will potentially recycle and reuse drill cuttings and bentonitic fluids by utilizing HydroLoc (a composting agent).
- E&P drilling wastes, including bentonitic drilling fluids will be re-used by land spreading on Noble spread fields per COGCC Rule 907.d.(3). No other E&P waste will be deposited at these locations.
 - Noble Mudfarms

| Site Name | Legal Description | Latitude/ Longitude | Driving Directions |
|----------------|--------------------|---------------------------|---|
| Sandau # 1 | Sec. 24, T4N, R66W | 40.278634, -104.729513 | NE of CR35 and CR 40 |
| Moser III | Sec 28 T3N R65W | 40.199951, -104.664102 | SW of the corner of WCR 30 and WCR 43 |
| Grover/Konig | Sec 10 T10N R62W | 40.850461, -104.312578 | 1 mile South of WCR 120 and WCR 79 |
| Miller I North | Sec 11 T6N R62W | 40.497715, -104.293745 | NE WCR 70 and WCR 81 |