

Michael Furtaw

Subject: RE: State Reportable Release Greenleaf

From: Dinkel, Mike

Sent: Tuesday, December 02, 2014 8:12 AM

To: Chris Canfield - DNR; 'rrudisill@co.weld.co.us'; Tom Parko (tparko@co.weld.co.us)

Cc: Schneider, Paul; Schwarz, Paul; Chase, Charles; Hamlin, Phil; Mickelson, Erik; LaRue, Sam

Subject: State Reportable Release

All, we had a State reportable release due to quantity on the location noted below. ~40 bbls of fresh water based drilling mud surfaced and was contained on the wellpad. The release was due to sandy soils and the drill rig losing circulation while drilling the surface hole. Please let me know if you have any questions.

Greenleaf 30N-2HZ

SESW 2-2N-65W

05-123-40619

Thanks,

Mike Dinkel, REM, CSEM

Sr. HSE Representative

Anadarko Petroleum Corporation

Office 720-929-6368

Cell 785-691-7788

[Click here for Anadarko's Electronic Mail Disclaimer](#)