

STATE OF
COLORADO

EnviroScan - DNR, OGCC <dnr_ogcc.enviroscan@state.co.us>

RE: Fwd: COGCC FIELD INSPECTION REPORT [Doc#667200663]

1 message

jerry@benchmarkenergy.us <jerry@benchmarkenergy.us>

Thu, Dec 11, 2014 at 11:09 AM

To: "Axelson - DNR, John" <john.axelson@state.co.us>

Cc: Greg Deranleau - DNR <greg.deranleau@state.co.us>, Britta Beckstead - DNR <britta.beckstead@state.co.us>, Kym Schure - DNR <Kym.Schure@state.co.us>, Rob Young - DNR <rob.young@state.co.us>, Craig Quint - DNR <craig.quint@state.co.us>, OGCC EnviroScan - DNR <ogcc.enviroscan@state.co.us>

We have no knowledge of where this waste came from. Its our belief that this has been there since before Benchmark Energy purchased the property. We will get samples, have them analyzed and dispose of this as required and file the proper forms.

Thanks

Jerry Nash

----- Original Message -----

Subject: Fwd: COGCC FIELD INSPECTION REPORT [Doc#667200663]

From: "Axelson - DNR, John" <john.axelson@state.co.us>

Date: Thu, December 11, 2014 10:13 am

To: [Jerry@benchmarkenergy.us](mailto:jerry@benchmarkenergy.us)Cc: Greg Deranleau - DNR <greg.deranleau@state.co.us>, Britta Beckstead - DNR <britta.beckstead@state.co.us>, Kym Schure - DNR <Kym.Schure@state.co.us>, Rob Young - DNR <rob.young@state.co.us>, Craig Quint - DNR <craig.quint@state.co.us>, OGCC EnviroScan - DNR <ogcc.enviroscan@state.co.us>

Mr. Nash,

The attached Field Inspection Report Doc #66720063 was submitted to Benchmark yesterday. I'm following up due to the stockpile of oily waste documented at the tank battery related to the NW Graylin D Sand Unit 8 (API #075-06002). Please see the pictures (document #s 667200747, 667200748) attached to the inspection. COGCC has no record of a spill reported at this location or a Form 27 for remediation of the oily waste.

No later than December 19, 2014, provide me with the following information:

- Submit an eForm 19 if the waste is the result of a reportable release as required by Rule 906;
- If you do not believe the waste is from a reportable release, provide the origin of the waste, the total volume and the date generated;
- Submit a Form 27 Remediation Plan to properly dispose of the oily waste;
- Any other localized occurrences of oily waste at the wellhead and battery shall be included in the Form 27 remediation plan.

If you have any questions, please call me at your earliest convenience.

John E. Axelson, P.G.
East Environmental Supervisor

P 303.894.2100 x5115 | F 303.894.2109 | C 303-916-0527

1120 Lincoln Street, Suite 801, Denver, CO 80203

john.axelson@state.co.us | www.colorado.gov/cogcc

Cc. Well File API #075-06002 - Correspondence Oily Waste Stockpile

----- Forwarded message -----

From: **COGCC Field Inspection Report** <dnr_eforms.helpdesk@state.co.us>

Date: Wed, Dec 10, 2014 at 4:19 PM

Subject: COGCC FIELD INSPECTION REPORT [Doc#667200663]

To: john.axelson@state.co.us, craig.quint@state.co.us, jerry@benchmarkenergy.us

Cc: kym.schure@state.co.us

DEPARTMENT OF NATURAL RESOURCES



**John W. Hickenlooper,
Governor**

1120 Lincoln St. Suite 801

Denver, CO 80203

Phone: (303) 894-2100

FAX: (303) 894-2109

www.cogcc.state.co.us

COGCC Field Inspection Report

ATTACHED REPORT HAS BEEN SUBMITTED TO COGCC DATABASE BASED ON FIELD INSPECTION RESULTS.

PLEASE REVIEW ENTIRE REPORT. COMMENTS, ACTION REQUIRED AND ALLEGED VIOLATIONS ITEMS ARE HIGHLIGHTED IN RED.