



Rev 8/2007

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax:(303) 894-2109

Date:

Complaint Report

This form may be submitted by any party with a complaint regarding oil and gas extractive operations. The complainant is to complete this form and mail to: COGCC, 1120 Lincoln St. Ste. 801, Denver, CO 80203 or fax to (303) 894-2109. COGCC will investigate the complaint and determine what action, if any, should be taken.

Complaint Taken By: ikenouyt

API Number: 05-123-39779

Facility ID: 437931

Doc Num: 200423542

Complainant Information

Name of Complainant: Craig Barr
Address: 2600 HWY 52
City: Kennesburg State: CO Zip: 80643

Phone: 970 815-2122

Work: .

Cell: .

Connection to incident (Land Owner, Royalty Owner, ect.): Resident

Fax: .

Email: circnova78@yahoo.com

Date Initial Contact Made: 02/10/2015

Description Of Complaint

Name of Operator: ENCANA OIL & GAS (USA) INC

OGCC Operator Number: 100185

Date of Incident: 2/10/2015 12:00:00 AM

Facility Name: Newnam

Type of Facility (Well, Tank, Battery, Flow Line, Pit): WELL
Well Name and Number:

QtrQtr: NENW Section: 32
Township: 2N Range: 64W

County:

Meridian: 6

Was the operator contacted? Y If yes, contact name: ENCANA OIL & GAS (USA) INC

Complaint Issues

<u>Category</u>	<u>Assigned to</u>	<u>Description</u>
LIGHTING	Jim Precup	The lights are highly visible at night due to the lack of any walls on the south side. Tommy Raye of Water Supply, LLC has told me that they are looking at Fracking the wells a month in advance and will become extremely noisy during that time period.
NOISE	Jim Precup	*Location: south east corner of weld county roads 51 and 16, Neuman is the surface owner* Encana has 3 drilling rigs that are drilling 24 wells. EnCana is drilling 24 wells on 4 pads, but has failed to fully enclose that they were going to use 3 rigs on the same location, did not fully enclose any of the 3 sites-forcing the sound south across frozen and open ponds and into the house which I am the tenant of. The water surfaces are reflecting the sound at a astounding rate, even with the distance in between the rigs and the house. The rigs are running the top gear boxes or tripping out of the holes at 1-3 am and waking me up from a dead sleep. This is causing undue stress on not only myself, but also my kids that reside here as well. This stress is causing the kids to not sleep well, have poor performance in school, behavior problems, and others to mention.

Other Notifications

<u>Date Notified</u>	<u>Party</u>	<u>Contact</u>	<u>Area Code</u>	<u>Phone</u>	<u>Email</u>	<u>Details</u>
2015/02/09		Wendy Weidembeck				Wendy has offered to have me go to a hotel of choice for a undisclosed period of time, allowing for rooms paid, meals, and travel as well. I refused that, as I do not like to go to hotels, and really seems like a cheap way out of the problems at hand. Wendy has stated that indeed the drilling rigs have been above the threshold in regards to sound, as there is a recording microphone outside of my bedroom window.