



Rev 8/2007

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax:(303) 894-2109

Date:

Complaint Report

This form may be submitted by any party with a complaint regarding oil and gas extractive operations. The complainant is to complete this form and mail to: COGCC, 1120 Lincoln St. Ste. 801, Denver, CO 80203 or fax to (303) 894-2109. COGCC will investigate the complaint and determine what action, if any, should be taken.

Complaint Taken By: ikenouyt

API Number: 05-123-41049

Facility ID: 159801

Doc Num: 200426630

Complainant Information

Name of Complainant: Craig Barr
Address: 26000 HWY 52
City: Keenesburg State: CO Zip: 80643
Connection to incident (Land Owner, Royalty Owner, ect.): Resident

Phone: 970 815-2122
Work: .
Cell: .
Fax: .
Email: CIRCNOVA78@YAHOO.CO
M

Date Initial Contact Made:**Description Of Complaint**

Name of Operator: VERDAD OIL & GAS
CORPORATION
Date of Incident: 3/17/2015 12:00:00 AM

OGCC Operator Number: 10485

Facility Name: Blackburn

Type of Facility (Well, Tank, Battery, Flow Line, Pit): WELL
Well Name and Number:

QtrQtr: NENE Section: 8
Township: 1N Range: 64W

County: Meridian: 6
Was the operator contacted? N If yes, contact name: VERDAD OIL & GAS CORPORATION

Complaint Issues

<u>Category</u>	<u>Assigned to</u>	<u>Description</u>
NOISE	Jim Precup	Noise can be heard and felt. Sounds like thumping. Started 3/12/15. During Daylight hours. Backup Alarms, Jake Brakes, bulldozers, belly dumps, scraper, roller packer, bull dozer, scraper, belly dumps, roller packer very brutal to wake up on a Friday morning at 6 am due to a bull dozer shining lights into my residence, back up alarms going full bore, and the tracks clanking away. No sound mitigation put in place at ALL!! Should be set to surface or "rat holed" by Wednesday the 18th of March. Ground is a dull rumble now due to the vibrator roller machine and can feel it in the kitchen of the residence. Operator never contacted me of the potential to drill at this location.
NOTIFICATION	Jim Precup	No notice letters were sent to my residence of drilling operations and the well is very potentially within 1,000 feet of the buildings.

Other Notifications