



Photo 1. View of erosional channel forming in southwestern portion of project area from well pad facing downslope.



Photo 2. View of southern portion of project area from southwestern corner facing eastward.





Photo 3. View of eastern portion of project area from southeastern corner facing northward.



Photo 4. View of northern portion of project area from northeastern corner facing westward.





Photo 5. View of western portion of project area from northwestern corner facing southward.