



STATE OF
COLORADO

EnviroScan - DNR, OGCC <dnr_ogcc.enviroscan@state.co.us>

Fwd: FW: Spaulding Field Corrective Actions from 3/18/15 Inspection

1 message

Fischer - DNR, Alex <alex.fischer@state.co.us>
To: OGCC EnviroScan - DNR <dnr_ogcc.enviroscan@state.co.us>
Cc: Kris Neidel - DNR <kris.neidel@state.co.us>

Thu, Apr 9, 2015 at 1:57 PM

Please upload this email attached photos with the following information:

Unique identifier (REM/Spill/NOAV #, etc.): Pit Facility IDs 115241, 112265, 112266, 112267, 112268, and 112269, REM 7058, and Location ID 324634
Document number (leave blank if one needs to be assigned):
Date received: 4/9/2015
Is data entry needed (Y/N): N
Notes: NA

Thanks!

-

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

----- Forwarded message -----

From: **James Hix** <jhix@olssonassociates.com>
Date: Thu, Apr 9, 2015 at 1:26 PM
Subject: FW: Spaulding Field Corrective Actions from 3/18/15 Inspection
To: "Fischer, Alex (Alex.Fischer@state.co.us)" <Alex.Fischer@state.co.us>, "kris.neidel@state.co.us" <kris.neidel@state.co.us>, "Gowen - DNR, Peter (peter.gowen@state.co.us)" <peter.gowen@state.co.us>
Cc: "Teff, John (johnt@cmproductionllc.com)" <johnt@cmproductionllc.com>, "Curtis Ditzell (curtis@cmproductionllc.com)" <curtis@cmproductionllc.com>, "Standifird, Brandon (brandons@cmproductionllc.com)" <brandons@cmproductionllc.com>, "Ryan Standifird (ryans@cmproductionllc.com)" <ryans@cmproductionllc.com>, "Roger Freeman (roger.freeman@dgslaw.com)" <roger.freeman@dgslaw.com>

Alex, Kris, and Peter,

Attached is an email from CM Production pertaining to the inspection findings on March 18, 2015. As stated below, CM Production constructed a containment berm around the stockpile on the east side of the access road that afternoon. Grady Camper had discussed this with me previously.

James

James W. Hix, PG| **Olsson Associates**

4690 Table Mountain Drive, Suite 200 | Golden, CO 80403 | jhix@olssonassociates.com

TEL 303.237.2072 | DIR 303.374.3139 | CELL 303.589.1572 | FAX 303.237.2659



From: Camper, Grady [mailto:gradyc@cmproductionllc.com]

Sent: Thursday, April 09, 2015 10:13 AM

To: James Hix

Cc: Teff, John; Curtis Ditzell; Ryan Standifird; Standifird, Brandon; Soliz, Fred; Camper, Grady

Subject: Spaulding Field Corrective Actions from 3/18/15 Inspection

James,

On March 18th, 2015 CM Production met with the COGCC at the Spaulding Field. Alex Fischer and Kris Neidel were the COGCC inspectors. Mr. Fischer brought to our attention that we needed to build a berm around the smaller stock pile of treated soil. We used native soil to build the berm to his specification that was verbally explained to us. We dug a trench 2' in depth along the lease road on the west side of the pile and used the native soil from the trench to build the berm on the east side of the treated soil pile. On the South side of the treated pile we built the same type of berm with same specifications. No treated soil was used in the construction of the berm. This was done in the afternoon of March 18th, after the COGCC inspectors left the Spaulding Field. Pictures are attached. We have also pumped the oil sheen fluid from Pit #3 to Pit #2 and added oil absorbent booms, since the inspection. Last fall we had Pit #3, #4 and #5 drained and partially dried. After the winter, snow melt caused the pits to have fluid again. We are working on getting #4 and #5 completely drained (to Pit #2) again so the soil can dry out. All fluid from the pits will be in Pit #1 and #2. The aerator is running to help with evaporation in Pit #2. As the fluid level goes down we will continue adding fluid from Pit #1 to Pit #2 so all fluid is evaporate and all pits can dry out. If there is any other pictures, descriptions or actions that need to be taken please let us know.

Thank you,

Grady Camper

(719) 371-2283

This email has been scanned by the Boundary Defense for Email Security System. For more information please visit <http://www.apptix.com/email-security/antispam-virus>

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

2 attachments



Berm1.jpg
282K



Berm2.jpg
283K