



March 24, 2015

Director Matthew Lepore
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203

RE: 317.p Exception
Carrizo (Niobrara) LLC
Legal Description: Section 29, Township 11 North, Range 57 West, 6th P.M.
Weld County, Colorado
Wells: O'Hare 2-29-11-57, API 123-40082
O'Hare 1-29-11-57, API 123-40081

Dear Director Lepore,

Carrizo (Niobrara) LLC hereby requests that the Director grant an exception under Rule 317.p. Carrizo was unable to get a resistivity log down to the kick off point (KOP) on both the O'Hare 1-29-11-57 and the O'Hare 2-29-11-57. Our plan forward is provide open hole logs for one of the two wells located to the south. An open hole log will be provided for either the O'Hare 1-32-11-57 [123-39467] or the O'Hare 2-32-11-57 [123-39744].

In addition, Carrizo will submit the CBL and measured-while-drilling gamma ray in all wells on the O'Hare 1-29-11-57 pad and the O'Hare 1-32-11-57 pad from TD to kick off point at time of completion filing.

Carrizo is certain that the logs to be provided at completion will satisfy the adequate description of the stratigraphy of the wellbore, will verify the depth of surface casing and also verify any aquifer coverage.

Thank you.

Respectfully,

Cynthia Pinel
Regulatory Compliance Analyst
Niobrara Oil & Gas Operations, Colorado, TX