




02469058

REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)

5-6-87 BCB #2
OS-103-05683
Location # 314427

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLS Discharged: 200 bbls BBLS Lost: ± 50 bbls.
3. Contained on location: Yes _____ No
4. Date and time of event: 5/6/87 ± 8:30 AM
5. Date and time reported to BLM: 5/7/87 7:58 AM Paul Onsager
6. Location of event: Fee 68, T2N, R102W, Sec 22, SE/SW
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event
N/A
8. Describe resultant damage:
\$2000.00
9. Time required for control of event: Immediately upon discovery
10. Action taken to control and contain:
Lateral valve shut-in. Small wash dammed up and water was picked up by vacuum truck. The rest soaked into ground.
11. Action taken to prevent recurrence:
*Did not reach a navigable waterway.
Repair made to pipe.
12. Cause of death:
N/A
13. Other agencies notified:
COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO - Steve Orzynsky 5/6/87 2:0
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only- 5-6-87
14. Other pertinent information:



Signature

T. L. Hurst
T. L. HURST

Date

5/14/87

Title

AREA SUPERVISOR

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.