




02469057



REPORT OF UNDESIRABLE EVENT

COLO. OIL & GAS CONSV. COMM.

NTL-3A (EFFECTIVE MARCH 1, 1979)

5-87 BCB #1

05-103-06274

Location # 397204

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLS Discharged: 500 bbls Inj. Wtr. BBLS Lost: 200 bbls
3. Contained on location: Yes _____ No X
4. Date and time of event: 5/1/87 10:30 AM
5. Date and time reported to BLM: 5/1/87 4:09 PM
6. Location of event: SENE Sec 32, R102W, T2N
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event

Split in pipe

8. Describe resultant damage:

N/A

9. Time required for control of event: ± 15 min.

10. Action taken to control and contain:
Shut off valve at Main Plant. Stinking Water Creek was dammed at Chevron Pipeline. Water sucked up in , Stinking Water. Creek, 200 bbls. soaked into ground.

11. Action taken to prevent recurrence:-

Pipe patched

12. Cause of death:

N/A

13. Other agencies notified:

COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO - Jim Keifer 5/4/87 8:45AM
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only May 6, 1987

14. Other pertinent information: J. Matheson, National Response Center, 5/1/87, 3:55 PM

Signature

T. L. Hurst

Date

5/11/87

Title

Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.